District I 1625 N French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr.

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 5 51.114				Sa	anta F	e, NM 875	005						
_			Rel	ease Notific	catio	n and Co	orrective A	ction	1	v			
Name of Company  Name of Company  Tandem Energy Corporation					OPERATOR								
				propration									
Address		x 1559, Mid	Telephone No. 361-935-9377										
	me BGSA	U 009B-5-9	Loco Hi	lls		Facility Typ		ection	4	•			
BALLARD Surface On	GRAYBUR	Lease No. 9B											
Surface Ov		Ecast No. 3B											
	03342		,			N OF RE							
Unit Letter	Section	Township	Range	Feet from the	North	n/South Line	Feet from the	East/\	Vest Line	County		•	
Н	8 18S 29E 1980 N		North	1	990	East		Eddy					
	-l	L	1	<u> </u>	<del></del>	7		<u>, —</u>					
						_	e <u>104.101849</u>						
Type of Rele	ease PW			NAI	UKE	Volume of Release 75 bbls Volume Recovered 25 bbls							
Source of Release						Date and Hour of Occurrence			Date and Hour of Discovery				
INJECTION LINE						4:41 p.m. 10/01/08 4:41				41 p.m. 10/01/08			
Was Immedi	iate Notice C	Given? ⊠	If YES, To Whom?										
		MIG DEMETE											
By Whom?		Date and Hour 10-1-08 4:40 P											
Was a Water	rcourse Reac		If YES, Volume Impacting the Watercourse.										
-2 111													
If a Waterco	urse was Imj	pacted, Descri	ibe Fully.*	•					•				
N/A					,								
Dosariba Car	use of Proble	em and Remed	dial Action	Takon *	·	· · · · · · · · · · · · · · · · · · ·							
Describe Cat	use of Proble	em and Kemed	nai Actioi	i Taken,"									
Injection line	e leak. The r	emedial actio	n plan wil	l be developed an	d execu	ited for the site	e after soil sampli	ing is co	nducted.				
Describe Are	ea Affected a	and Cleanup A	ction Tak	en * .		<del></del>			·····	<del></del>			
Describe 7the	a miceted a	ina Cicanup r	iction rak	Cii.									
	e leak 335' x	12'. Release	d 75 bbls a	and recovered 25	bbls. T	he remediatio	n plan will be dev	veloped	and execute	ed based up	on the s	oil analysis	
results.													
				is true and compl									
				d/or file certain re									
				e of a C-141 repo investigate and re									
or the environ	nment. In ad	ldition. NMO	dequatery CD accent	ance of a C-141 r	enort d	oes not relieve	the operator of r	esnonsil	oility for co	mnliance wa	ith anv	other	
federal, state,	or local law	s and/or regul	lations.		-p		me operator of t	-op on si	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
						,	OIL CONS	SERV	ATION I	DIVISIO	N		
0.	Bary Stra	acknown 196	STOPA.	يد السارجور									
Signature:			·····		Approved by District Comments				Remediation Actions to be completed and Final C-141 submitted with confirmation				
Printed Name: Brandi Barthels						Approved by District Supervisor:			analyses/documentation on or before the				
										piration Date.		-	
Title: Regula	tory & Envi	ronmental Af	fairs Mana	ger		Approval Date	10-08-08	<u> </u> E	xpiration D	ate: 12	-08-	08	
F-mail Addre	ess hharthal	s@nlateenera	v com			Conditions of	Annroval				/		
E-mail Address: bbarthels@plateenergy.com						Conditions of Approval:				Attached			

Date: 10/02/08 \* Attach Additional Sheets If Necessary Phone: 361.935.9377

SEB 082.8241728

Within 30 days, on or before 11-08-08, completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage.

2RP-243 Notify OCD 48 hours prior to

obtaining samples where analyses are to be presented to OCD