

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

AUG 29 2008

OCD-ARTESIA

Release Notification and Corrective Action

ISEB0827640747

nSEB0827639030

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Platinum Energy/Tandem Energy Corp.	Contact	Brandi Barthels
Address	120 S. Main St., Suite 350 Victoria, Texas 77901	Telephone No.	1-361-935-9377
Facility Name	BGSAU 20-6	Facility Type	Water injection
Surface Owner BLM		Mineral Owner BLM	Lease No. NM14843

30 015 21796

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	17	18S	29E	760	North	560	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release	Volume Recovered
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Produced water line broke. The leak was stopped immediately. Soil sampling will be conducted and a remedial action plan will be developed and executed.		
Describe Area Affected and Cleanup Action Taken.* The area affected is approximately 60'X300'. Cleanup action taken included a vacuum truck which came on site immediately to recover the produced water. The remedial action plan will be developed and executed for the site after soil sampling is conducted.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brandi Barthels</i>	OIL CONSERVATION DIVISION	
Printed Name: Brandi Barthels	Approved by District Supervisor: <i>TEunh, SB</i>	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.
Title: Regulatory & Environmental Affairs Manager	Approval Date: 10-2-08	Expiration Date: 12-8-08
E-mail Address: bbarthels@platenergy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 8-22-08 Phone: 361.935.9377	Within 30 days, on or before <u>Nov 13, 2008</u> , completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage	
Notify OCD 48 hours prior to obtaining samples where analyses are to be presented to OCD		

* Attach Additional Sheets If Necessary

SEB0827640963

-2RP - 231