

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 10 2008
OCD-ARTESIA
Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation <u>236183</u>	Contact	Brandi Barthels
Address	120 S. Main Street, Suite 350 Victoria, TX. 77901	Telephone No.	361-935-9377
Facility Name	Lothian	Facility Type	South Lucky Lake Queen #22
Surface Owner		Mineral Owner	Lease No.

30-005-60350

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	22	15S	29E	1980	FNL	660	FWL	Chavez

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	saltwater/oil	Volume of Release	8 BBLS oil, 15 BBLS saltwater	Volume Recovered	0 BBLS
Source of Release	Flowline leak.	Date and Hour of Occurrence	11/05/08 1:45 p.m.	Date and Hour of Discovery	11/05/08 1:45 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher @ OCD ; Mike Meghee @ BLM			
By Whom?	Brandi Barthels	Date and Hour Mike Bratcher 1:50 p.m.; Mike Meghee 2:00 p.m.			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Flowline leak from header. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.*

Estimated area affected 3 1/2 x 200'. None recovered. The remediation plan will be developed and executed based upon the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Brandi Barthels</u>	OIL CONSERVATION DIVISION	
Printed Name: Brandi Barthels	Approved by District Supervisor: <u>T. Gumbly SB</u>	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.
Title: Regulatory & Environmental Affairs Manager	Approval Date: <u>11-19-08</u>	Expiration Date: <u>1-19-09</u>
E-mail Address: bbarthels@platenergy.com	Conditions of Approval: Within 30 days, on or before <u>12-19-08</u> , completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage.	Attached <input checked="" type="checkbox"/> <u>2RP - 271</u>
Date: 11/06/08 Phone: 361.935.9377		

* Attach Additional Sheets If Necessary

Notify OCD 48 hours prior to
obtaining samples where analyses
are to be presented to OCD