

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NOV 10 2008

OCD-ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Tandem Energy Corporation	Contact Brandi Barthels
Address 120 S. Main Street, Suite 350 Victoria, TX. 77901	Telephone No. 361-935-9377
Facility Name Lothian	Facility Type East Red Lake Battery

~~EAST RED LAKE UNIT 002~~

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

30-015-01297

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	1	17S	28E	660	FNL	330	FWL	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release saltwater	Volume of Release 8 BBLS	Volume Recovered 2 BBLS
Source of Release Water tank ran over.	Date and Hour of Occurrence 4:00 p.m. 11-03-08	Date and Hour of Discovery 4:00 p.m. 11-03-08
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

Water tank ran over. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.\*

Estimated 70' x 10' area affected. The remediation plan will be developed and executed based upon the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Brandi Barthels	Approved by District Supervisor: 	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date
Title: Regulatory & Environmental Affairs Manager	Approval Date: 11-19-08	Expiration Date: 1-19-09
E-mail Address: bbarthels@platenergy.com	Conditions of Approval: Within 30 days, on or before 12-19-08, completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage.	
Date: 11/04/08 Phone: 361.935.9377	Attached <input checked="" type="checkbox"/> 2RP - 273	

\* Attach Additional Sheets If Necessary

Notify OCD 48 hours prior to  
obtaining samples where analyses  
are to be presented to OCD