

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NOV 10 2008  
Form C-141  
Revised October 10, 2003  
OCD-ARTESIA  
submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Tandem Energy Corporation	Contact Brandi Barthels
Address 120 S. Main Street, Suite 350 Victoria, TX. 77901	Telephone No. 361-935-9377
Facility Name Lothian	Facility Type Turkey Track #3

<del>TURKEY TRACK SEC 3 UNIT 003</del> Surface Owner	Mineral Owner	Lease No.
---	---------------	-----------

30-05-10454

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B/C	3	19S	29E	1315	FNL	2635	RWL	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release saltwater	Volume of Release 200 BBLS	Volume Recovered 70 BBLS
Source of Release Water tank ran over.	Date and Hour of Occurrence 11/05/08 4:00 p.m.	Date and Hour of Discovery 11/05/08 4:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher @ OCD 7:50 p.m. by voicemail. Jim Amos @ BLM 7:55p.m.	
By Whom? Brandi Barthels	Date and Hour 11/05/08 7:45 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Possible hole in tubing or injection packer. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.\*  
Estimated area affected 90' x 190'. The remediation plan will be developed and executed based upon the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Brandi Barthels</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Brandi Barthels	Approved by District Supervisor: <u>TGum by SB</u>	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date
Title: Regulatory & Environmental Affairs Manager	Approval Date: <u>11-19-08</u>	Expiration Date: <u>1-19-09</u>
E-mail Address: bbarthels@platenergy.com	Conditions of Approval: Within 30 days, on or before <u>12-19-08</u> , completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage.	Attached <input checked="" type="checkbox"/> <u>2RP - 272</u>
Date: 11/06/08 Phone: 361.935.9377		

\* Attach Additional Sheets If Necessary

Notify OCD 48 hours prior to obtaining samples where analyses are to be presented to OCD