

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-33428
Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 505-748-1471	
Facility Name Dazed BDZ Federal Com. #2	API Number 30-015-33428	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-0230377-B
--------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter E	Section 3	Township 21S	Range 24E	Feet from the 3400	North/South Line South	Feet from the 660	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.51079 Longitude 104.49284



NATURE OF RELEASE

Type of Release Condensate & Produced Water	Volume of Release 5 B/O and 5 B/W	Volume Recovered 0 B/O & 0 B/W
Source of Release Water Tank	Date and Hour of Occurrence 4/3/2006 PM	Date and Hour of Discovery 4/3/2006 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
Well unloaded more water than normal, causing water tank to overflow. A second tank will be installed.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 5' X 35', inside bermed area. Contaminated soils excavated and placed on plastic. Soils taken to an OCD approved facility. Samples taken (6/20/2006; 9/10/2007 & 9/20/2007), continued excavating contaminated soils until sample results were within OCD Guidelines for the site ranking. All excavated soils were taken to an OCD approved facility. **Depth to Ground Water: 50'-99' (approx. 65'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. With enclosed information, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION 	
Printed Name: Robert Asher	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date: 12/15/08	Expiration Date: N/A
E-mail Address: boba@ypcnm.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: Thursday, December 27, 2007	Phone: 505-748-4217	

* Attach Additional Sheets If Necessary

2RP-28