

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DEC 22 2008

OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

14049 OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company <u>Marbob Energy Corporation</u>		Contact <u>Rand French</u>	
Address <u>P.O. Box 227 Artesia, NM 88211</u>		Telephone No. <u>575-748-3303</u>	
Facility Name <u>Nuose Fed #1</u>		Facility Type <u>Tank Battery</u>	
Surface Owner <u>BLM</u>		Mineral Owner <u>BLM</u>	
Lease No. <u>nmnm 113927</u>			

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>C</u>	<u>35</u>	<u>19S</u>	<u>25E</u>	<u>1650</u>		<u>2310</u>		<u>Eddy</u>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <u>overflow of tank Battery</u>	Volume of Release <u>25 barrels</u>	Volume Recovered <u>23</u>
Source of Release <u>Tank Battery</u>	Date and Hour of Occurrence	Date and Hour of Discovery <u>12/14/08 7:00 am</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Mike Bratcher - Artesia District office</u>	
By Whom? <u>Rand French</u>	Date and Hour <u>12/14/08 9:40 am</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <u>N/A</u>	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Overflowed tank Battery:
All fluid except for fluid that seeped around the clean pipes, was contained inside of berm and the plastic underliner.

Describe Area Affected and Cleanup Action Taken.*

Area effected was small spots outside of Berm and inside Berms. Plastic liner below tanks contained fluid. Vacuum sucked fluids, removed gravel, and disposed of to Lea Landfill, clean & removed stained soils outside of berm & hauled off.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Rand French</u>	Approved by District Supervisor: <u>Gene By SB</u>	
Printed Name: <u>Rand French</u>	Approval Date: <u>1-6-09</u>	Expiration Date: <u>N/A</u>
Title: <u>Biologist</u>	Conditions of Approval: <u>N/A</u>	Attached <input type="checkbox"/> <u>N/A</u>
E-mail Address: <u>wildlife@marbob.com</u>		
Date: <u>12/19/08</u> Phone: <u>748-3303</u>		

* Attach Additional Sheets If Necessary