

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

DEC 12 2008

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD-ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

13EB0900254386

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name - Aoudad State #1		Facility Type-	Battery

Surface Owner	BLM	Mineral Owner		Lease No. API#	30-015-32365
---------------	-----	---------------	--	----------------	--------------

30 015 32365

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	36	17S	31E	2310	North	330	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release- Water	Volume of Release-60 bbls	Volume Recovered- 55bbls
Source of Release- 3" poly line	Date and Hour of Occurrence- 12/08/08- 2:30pm	Date and Hour of Discovery 12/08/08-2:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher w/OCD.	
By Whom? Kanicia Carrillo	Date and Hour December 8, 2008, 4:56pm.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Leak on the 3" poly line. Repaired poly line with new connections.

Describe Area Affected and Cleanup Action Taken.*
The area affected was 20' x 100' in the pasture. 200 yards SE of the #1 well. We have a vacuum truck on location and will remove any contaminated soil. Tetra Tech will turn in soil samples and final report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Kanicia Carrillo		Approved by District Supervisor: 	
Title: Regulatory Analyst		Approval Date: 1-2-09	Expiration Date: 3-2-09
E-mail Address: kandicarrillo@conchoresources.com		Conditions of Approval:	
Date: 12/09/08 Phone: 432-685-4332		Attached <input checked="" type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP - 287