



ARDINAL LABORATORIES

PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
LCX ENERGY
ATTN: ALIN RICHARDSON
110 N. MARIENFELD, SUITE #200
MIDLAND, TX 79701
FAX TO: (432) 687-2521, (575) 622-0233
& (575) 578-0180

Receiving Date: 07/11/08
Reporting Date: 07/14/08
Project Number: 1921
Project Name: STATE COM 21
Project Location: EDDY COUNTY, NM

Analysis Date: 07/11/08
Sampling Date: 07/10/08
Sample Type: SOIL
Sample Condition: INTACT
Sample Received By: ML
Analyzed By: KS

30-015-34980

LAB NUMBER	SAMPLE ID	Cl ⁻ (mg/kg)
H15153-1	NW	16,800
H15153-2	NE	3,440
Quality Control		500
True Value QC		500
% Recovery		100
Relative Percent Difference		2.0

METHOD: Standard Methods 4500-Cl-B

Note: Analyses performed on 1:4 w:v aqueous extracts.

Kristen Supplee
Chemist

07/14/08
Date

H15153 LCX

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



CARDINAL LABORATORIES

101 East Marland, Hobbs, NM 88240 2111 Beechwood, Abilene, TX 79603

(505) 393-2326 FAX (505) 393-2476 (325) 673-7001 FAX (325) 673-7020

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Company Name: L C X ENERGY				BILL TO				ANALYSIS REQUEST															
Project Manager: Allen Richardson				P.O. #:																			
Address: 110 N Marine Field # 200				Company:																			
City: Midland State: TX Zip: 79701				Attn:																			
Phone #: 432-262-4011 Fax #: 432-687-2521				Address:																			
Project #: 1921 Project Owner:				City:																			
Project Name: State Com 21				State: Zip:																			
Project Location: Eddy Co.				Phone #:																			
Sampler Name: Henry				Fax #:																			
FOR LAB USE ONLY				MATRIX		PRESERV.		SAMPLING															
Lab I.D.	Sample I.D.	(GRAB OR C/COMP)	# CONTAINERS	GROUNDWATER	WASTEWATER	SOIL	OIL	SLUDGE	OTHER:	ACID/BASE:	ICE / COOL	OTHER:	DATE	TIME									
H15153-1	NW	G	1			/							7/1/08	11:38	X								
-2	NE	G	1			/							1	11:40	X								

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising whether based in contract or tort, shall be limited to the amount paid by the client for the analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or subcontractors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise.

Relinquished By:	Date: 7-11-08	Received By:	Phone Result: <input type="checkbox"/> Yes <input type="checkbox"/> No	Add'l Phone #:
Time: 1:20			Fax Result: <input type="checkbox"/> Yes <input type="checkbox"/> No	Add'l Fax #:
Relinquished By:	Date:	Received By:	REMARKS:	
Time:			Phone results to Mike Nicols 505-420-1942	
			Daymond Box 505-910-6119	
			Fax # Mike 505 622-0223	
			Email To Mike Brasher @STNM.COM	
Delivered By: (Circle One)	Sample Condition	CHECKED BY:		
Sampler - UPS - Bus - Other:	Cool Intact	(Initials)		
	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476