

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

nmcs0333752991

Release Notification and Corrective Action

70-011-32599		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company ChevronTexaco		Contact Danny Lovell			
Address 601 E. Greene Carlsbad NM		Telephone No. 505-887-5676 (office) 505-390-0866 (cell)			
Facility Name Skelly Unit 940		Facility Type Production			
Surface Owner Federal		Mineral Owner Federal		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
Ur A	22	17S	31E	990	North	330	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 40 BW	Volume Recovered 40 BW
Source of Release Water Tank	Date and Hour of Occurrence 11/15/03	Date and Hour of Discovery 7:30 a.m. 11/15/03
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Stubblefield. Immediate notice was not given because facility is lined and bermed so Field Specialist assumed it was not necessary to report as a spill. Also notified Paul Evans with BLM.	
By Whom? Danny Lovell	Date and Hour 11/19/03	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

4" flange on water tank was not properly tightened and when tank started filling with water flange leaked.


NOV 26 2003

OCD-ARTESIA

Describe Area Affected and Cleanup Action Taken.*

This a new Facility which is lined and bermed. All fluid was contained within berm and vacuumed up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Danny Lovell		Approved by District Supervisor: TIM W. GUM	
Title: Operations Supervisor		Approval Date: 12/3/03 DISTRICT II SUPERVISOR <i>M.S.</i> Expiration Date:	
E-mail Address: LOVD@ChevronTexaco.com		Conditions of Approval:	
Date: 11/21/03 Phone: 390-0866		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary