

District I  
1625 N. French Dr, Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JUN 30 2009

Form C-141  
Revised June 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-36467

Release Notification and Corrective Action

NMLB 0920853986

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC 229137	Contact: Pat Ellis
Address: 550 W. Texas, Suite 1300, Midland, Tx 79701	Telephone No. (432) 683-7443
Facility Name: Electra Federal North Battery	Facility Type: Tank Battery



Surface Owner Charles Martin	Mineral Owner Unknown	Lease No. API# 30-015-36467
------------------------------	-----------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter B	Section\ 10	Township 17S	Range 30E	Feet from the 1170'	North Line North	Feet from the 2310'	East Line East	County Eddy
------------------	----------------	-----------------	--------------	------------------------	---------------------	------------------------	-------------------	----------------

NATURE OF RELEASE

Type of Release Oil	Volume of Release 150 BBLs	Volume Recovered 90 BBLs
Source of Release Tank Overflowed	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 03/05/09 - 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? C	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Tank overflowed and was contained within firewall. Site was vacuumed and soils excavated.		
Describe Area Affected and Cleanup Action Taken.* All oil was contained within firewall. COG Operating LLC vacuumed all liquids from ground and as of 03/06/09 dug and removed soils. Tetra Tech sampled site on 03/10/09. Upon completion of delineation, remaining hydrocarbon impacted soils were excavated and removed offsite for proper disposal.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Jeffrey Kindley as agent for COG		Signed By:  Approved by District Supervisor:	
Title: Division Senior Environmental Geologist		Approval Date: JUL 27 2009	Expiration Date: N/A
E-mail Address: jeff.kindley@tetratech.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 06/24/09 Phone: (432) 682-4559			

\* Attach Additional Sheets If Necessary

2RP-324