

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 22 2009

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-33198

Release Notification and Corrective Action

n SEB0835030121

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name -	Red Lake Sand Unit #45	Facility Type-	Battery

Surface Owner	State	Mineral Owner		Lease No.	API# 30-015-33198
---------------	-------	---------------	--	-----------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	20	17S	28E	990	South	990	East	Eddy

Latitude 32.8150641048197 Longitude -104.19250

NATURE OF RELEASE

Type of Release-	Water/oil	Volume of Release-	2 bbls	Volume Recovered-	none
Source of Release-	Valve leaked	Date and Hour of Occurrence-	11/21/08- 10:30am	Date and Hour of Discovery	11/21/08- 10:30 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Kimberly Wilson	Date and Hour	11/21/08 10:30am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Pinhole size leak at valve Valve repaired

Describe Area Affected and Cleanup Action Taken.*

This was a very small spill A valve leaked spraying oil and water which began pooling on the ground and flowing west off the location then south into a field. 2' X 15' 12/11/08 We dug out all saturated/contaminated soil and then hauled to a land fill. Replaced soil with clean back fill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Kanicia Carrillo	Approved by District Supervisor 	Signed By	
Title: Agent	Approval Date: SEP 30 2009	Expiration Date: N/A	
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>	
Date: 01/13/09	Phone: 432-685-4332		

* Attach Additional Sheets If Necessary