

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCT 15 2009

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-34645

Release Notification and Corrective Action

NMLB 0927454488

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Chasity Jackson
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-686-3087
Facility Name - Skelly Unit 942		Facility Type-	Battery

Surface Owner	Federal	Mineral Owner		Lease No.	30-015-34645
---------------	---------	---------------	--	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	22	17S	31E	1210	North	2195	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release-Produced Water	Volume of Release-30bbbls	Volume Recovered- 26bbbls
Source of Release- Water Tank	Date and Hour of Occurrence- 6/8/09- 7:00 am	Date and Hour of Discovery 6/8/09-7:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bracher NMOCD District 2, Eddy Co. Terry Gregston BLM	
By Whom? Pat Ellis	Date and Hour 6/9/09 @ 1:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Water Tank ran over due to too much volume entering facility. Decrease volume by rerouting water to SWD.

Describe Area Affected and Cleanup Action Taken.\*

All water was contained inside firewall at facility. All standing fluid was removed; all contaminated soil will be removed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>C Jackson</u>	OIL CONSERVATION DIVISION	
Printed Name: Chasity Jackson	Approved by District Supervisor <u>Mike Bracher</u>	
Title: Agent for COG	Approval Date: <u>OCT 01 2009</u>	Expiration Date:
E-mail Address: <u>cjackson@conchoresources.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/10/09	Phone: 432-686-3087	

\* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL BY: Remediation Project

2 RP-347

NMLB 0927454488