

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27936

Release Notification and Corrective Action

NMLB 0935637592

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy USA WTP	16696	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd		Telephone No.	(575) 397-8247
Facility Name	Sterling Silver 34 Fed # 2 Battery		Facility Type	Battery

Surface Owner	BLM	Mineral Owner	Shared	Lease No.	
---------------	-----	---------------	--------	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	34	23s	31e					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produce Water	Volume of Release	250 bbls	Volume Recovered	130 bbls
Source of Release	Swedge off tank	Date and Hour of Occurrence	10/22/09	Date and Hour of Discovery	same
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Bratcher, Mike		
By Whom?	Dusty Wilson	Date and Hour	10/22/09 @ 11.10 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Swedge broke off of tank going to transfer pump. Swedge was repaired. Emptied tank contents out into fire wall area of battery. Spill did stay within the firewalls at the battery. Remediation to be determined.

Describe Area Affected and Cleanup Action Taken.*


Remediate to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dusty L. Wilson	Approved by: 	
Title: HES Specialist	Approval Date: DEC 21 2009	Expiration Date:
E-mail Address: dusty.wilson@oxy.com	Conditions of Approval:	attached <input checked="" type="checkbox"/>
Date: 10/22/09	Phone: (575) 397-8244	

• Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: 
& approved at local

2RP-372

NMLB 0935645327