Submit to Appropriate Distric	et Office	$\top$	St	ate of No	ew Me	xico							Form C-1	
District Energy, Minerals and Natural Resou						source	es L	July 17, 2008						
1625 N French Dr., Hobbs, NM 88240 District II.								1. WELL API NO.						
1301 W Grand Avenue, Artesia, NM 88210 OIL CONSERVATION DIVISION							-	30-015-28431						
1000 Rio Brazos Rd , Aztec, NM 87410 <b>ENTERED</b> 1220 South St. Francis Dr.								2. Type			ee 🗀 r	EED/INIDIAN	,	
District IV 1220 S St Francis Dr , Santa Fe, NM 87505									$\dashv$					
WELL COMPLETION OR RECOMPLETION REPORT AND LOG									, ` ` .	,				
4. Reason for filing									5 Lease N	lame or			lame	7
COMPLETION REPORT (Fill in boxes #1 through #31 for State and Fee wells only)  C-144 CLOSURE ATTACHMENT (Fill in boxes #1 through #9, #15 Date Rig Released and #32 and/or #33; attach this and the plat to the C-144 closure report in accordance with 19.15 17 13 K NMAC)  JAN 13 2010								IVED 2010	H					
#33; attach this and the pl  9 Type of Completion	at to the C-144 c	losure rep	ort in accordan	ce with 19.1:	5 17 13 K	NMAC)			7					H
NEW WELL 8 Name of Operator	☐ workove	R 🗆 I	DEEPENING [	X PLUGBA	аск 🗆	DIFFER	ENT RE	SERVO	OIR C			OCD A	RTESIA	Ц
Nearburg Produc	cing Compan	у					·		01574					
10. Address of Operator									11 Pool					
3300 N A St., E					- I.								Glorieta/	<u>Yes</u>
12. Location Unit Let			Township	Range	Lo	t	Feet from		N/S Line	+		E/W Lin		
Surface. H	22	<u>'</u>	195	25E			165	00	N	+	990	<u>E</u>	Eddy	
t	1. Date T.D. Rea	ched	15. Date Rig	Released	l	16. Da	te Comp	leted (R	eady to Pro	duce)	17	Elevation	S (DF & RKB,	
11/4/09	NA		NA NA			1	1/20/0		oudy to Tre	,uucc)	RT	, GR, etc )	3455	
<ol> <li>18. Total Measured Dept</li> <li>8164</li> </ol>	h of Well		19 Plug Bac 3926	k Measured	Depth	20. Wa		ional Su	ırvey Made	ı	1. Туре <b>NO</b>	Electric ar	nd Other Logs R	lun
22 Producing Interval(s) 2347-2787 (OA)	, of this completi	on - Top,								T				
23	. ^		CASING R				ings se							
CASING SIZE WEIGHT LB./FT.						Ci	CEMENTING RECORD AMOUNT PULLEI			D				
9-5/8 36				<u> 14-3/4</u>		1200					Surface			
	7 23 & 26			64		8-3/4			12	1200 NA			NA	
Csg is existing	<del> </del>		~	,										
	<del> </del>		ļ						······································				····	
24.	.1	LIN	ER RECOR	D				25.		LIBIN	G RE	CORD		
	OP	BOTT		SACKS CE	MENT	SCR	EEN	SIZE			DEPTH:		PACKER SE	Г
	<u> </u>					T		2-7	7/8		2730	· · · · · ·		
26. Perforation record (i	nterval, size, and	number)							ACTURE,					
7703-7828 - CIBF				DEPTH		/AL					IAL USED			
2347-2787 - 1 JS		es)	7703 - 7828 2347 - 2787						HCL a					
						2347-2	.707		See F	iccac	neu si	ileet		
28.				PRO	ODUC	TION								
Date First Production 11/20/09	Produ Pum		thod (Flowing	, gas lift, pur	npıng - Sı	ze and type	e pump)				Well Sta Produ		or Shut-ın)	
Date of Test 12/17/09	Hours Tested 24		Choke Size	Prod'n Fo Test Perio		Dil - Bbl 18		ias - MC 50		Vater - 18	Bbl	Gas - 682:	Oil Ratio 1	
Flow Tubing Press	Casing Pressure	e (	Calculated 24- Hour Rate	Oil - Bbl	•	Gas - M	CF	ł	er - Bbl.			vity - API -	(Corr)	
300	55			88		60		118	1 22	Text	38.2			
29. Disposition of Gas (Sold, used for fuel, vented, etc.)  Sold									30 Test Witnessed By C Hensley					
31. List Attachments														
C104	used at the well	, attach a	plat with the lo	cation of the	temporar	y pit.								
	, about at the worl													
32 If a temporary pit was		l, report t	he exact location	on of the on-s				Longit	tude			NAD:	1927 198	33
32 If a temporary pit was 33. If an on-site burial was  I hereby certify that the Signature	as used at the well	hown on		Latitude this form is d	true and				my knowi			ief	1927 198 te/-/2-/	

## **INSTRUCTIONS**

This form is to be filed with the appropriate District Office of the Division not later than 20 days after the completion of any newly-drilled or deepened well and not later than 60 days after completion of closure. When submitted as a completion report, this shall be accompanied by one copy of all electrical and radio-activity logs run on the well and a summary of all special tests conducted, including drill stem tests. All depths reported shall be measured depths. In the case of directionally drilled wells, true vertical depths shall also be reported. For multiple completions, items 11, 12 and 26-31 shall be reported for each zone.

## INDICATE FORMATION TOPS IN CONFORMANCE WITH GEOGRAPHICAL SECTION OF STATE

South	heastern ]	New Mexico	Northeastern New Mexico			
T. Anhy		T. Canyon	7637	T. Ojo Alamo	T. Penn. "B"	
T. Salt		T. Strawn		T. Kirtland-Fruitland	T. Penn. "C"	
B. Salt		T. Atoka		T. Pictured Cliffs	T. Penn. "D"	
T. Yates		T. Miss		T. Cliff House	T. Leadville	
T. 7 Rivers		T. Devonian		T. Menefee	T. Madison	
T. Oueen		T. Silurian		T. Point Lookout	T. Elbert	
T. Grayburg		T. Montoya		T. Mancos	T. McCracken	
T. San Andres	723	T. Simpson		T. Gallup	T. Ignacio Otzte	
T. Glorieta	2380	T. McKee		Base Greenhorn	T. Granite	
T. Paddock		T. Ellenburger		T. Dakota	T	
T. Blinebry		T. Gr. Wash		T. Morrison	T.	
T. Tubb		T. Delaware Sand		T. Todilto	T.	
T. Drinkard		T. Bone Springs	3927	T. Entrada	T.	
T. Abo		T.Spring SS	5873	T. Wingate	T.	
T. Wolfcamp	6090			T. Chinle	T.	
T. Penn		T.		T. Permain	T.	
T. Cisco (Bough C)		Т.		T. Penn "A"	T.	
					OIL OR GAS	

			SANDS OR ZONES
No. 1, from	to	No. 3, from	to
No. 2, from	to	No. 4, from	to
	IMPORT	TANT WATER SANDS	
Include data on rate of water	inflow and elevation to which w		
No. 1, from	to	feet	
No. 2, from	to	feet	
No. 3. from	to	feet	
ı	LITHOLOGY RECO	ORD (Attach additional sheet if	necessary)

From	То	Thickness in Feet	Thickness in Feet Lithology		То	Thickness in Feet	Lithology
723	2380	1657	dolomite, chert, shale, sand				
2380	3927	1547	sand, dolomite, chert				
3927	5873	1946	limestone, shale, sand				
5873	6090	217	sand, dolomite, sand				
6090	7637	1547	shale, dolomite, sand, ss, limestone				

## TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

## B & B #7

1,650' FNL and 990' FEL, Section 22, T19S, R25E

Dagger Draw; Upper Penn, North

Eddy County, New Mexico

\*\* ALL COSTS ARE FIELD ESTIMATES \*\*

11/14/09

MIRU BJ Services pump trucks to frac well dn csg. RU Stinger csg saver on top of frac valve on wellhead. BJ tested lines to 5200#. Open well w/ 4# csg pressure. Start pumping 52.1 Bbls HCL acid ahead of pad @ 15 bpm w/ 1194# csg pressure. Staged to 1071.4 Bbls Slick water pad (consisting of fresh wtr w/ 1.5 gpt FRW-14, 1 gpt Clay treat 3C, 1 gpt NE-940, 0.25 gpt ALPHA-125) @ 58.5 bpm w/ 3230#. Staged to .50# Super LC 20/40 sand w/ 974.5 Bbls Slick water pumped. The following is a breakdown of proppant/sweeps pumped:

Current Operation: Flow well back to frac tank.

	Bbls		
Csg Psi	Pumped	BPM	Description
3176#	974.5	60.5	0.50# (ppg) Super LC 20/40 resin coated sand w/ activator
2890#	238.4	60.7	Sweep (displace .5# sand from csg w/ slick water)
2880#	985.5	60.6	0.75# (ppg) Super LC 20/40 resin coated sand w/ activator
2770#	238.2	60.2	Sweep (displace .75# sand from csg w/ slick water)
2939#	996.5	60.3	1.0# (ppg) Super LC 20/40 resin coated sand w/ activator
2981#	238.5	60.2	Sweep (displace 1.0# sand from csg w/ slick water)
3440#	350	60.3	1.50# (ppg) Super LC 20/40 resin coated sand w/ activator
3200#	260	60	Sweep (displace 1.5# sand from csg w/ slick water)
3260#	481	60	1.0# (ppg) Super LC 20/40 resin coated sand w/ activator
3251#	238	60	Sweep (displace 1.0# sand from csg w/ slick water)
2830#	581	60.1	1.0# (ppg) Super LC 20/40 resin coated sand w/ activator
3020#	310	60	1.25# (ppg) Super LC 20/40 resin coated sand w/ activator
3040#	174	60	1.50# (ppg) Super LC 20/40 resin coated sand w/ activator
3122#	89.2	60	Flush 2 Bbls short of top perf

Shutdown pumps. ISDP @ 1580#. 5 min- 1249#, 10 min- 1228#, 15 min- 1214#. Treating pressures: MAX- 3450#, MIN- 1194#, AVG- 3100#. Injection rates: Treating fluid- 60.6 bpm, Flush- 60 bpm. RD Stinger csg saver. RDMO BJ Services pump trucks. Have 7044 Bbls load wtr to recover. RU Pro well testing flowback flange up to wellhead. Left well shut in overnight for resin to set. Will start flowing well back to frac tank in the AM. Pumped a total of 200,140# Super LC 20/40 proppant into well. BJ dens meter read sand volume to be 197,547# pumped. Dens meter calculated to be 11.2% short which meant we were probably 0.2 ppg low on the sand concentration being displayed. The friction reducer was approx 41% short also.

Note: Was designed to go to 2.5# (ppg) Super LC 20/40 then flush. Was unable to get all 1.5# sand stage as scheduled due to running close to maximum csg pressure. Swept 1.5# and started 1.0# sand. Pumped enough 1.0# sand to sweep then started 1.0# to 1.5# ramp on last stage before going to flush to put away all sand that was in the sand king.