Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

000	A-torio
ULD	Artesia

5 2010

epartment or agency of the United'S CARLSBAD FIELD OFFICE

5 Lease Serial No. NM-102036

6. If Indian, Allottee or THINGED ARTESIA

abandoned well.	Use Form 3160-3 (A	PD) for such	proposals.					
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.				
1 Type of Well ☑ Oɪl Well ☐ Gas Well ☐ Other					8. Well Name and No. RDX 15-8			
2 Name of Operator RKI - Exploration & Production, LLC				9 API Well No. 30-015-36758				
3a. Address 3b. Phone No. (include area code))	10. Field and Pool or Exploratory Area			
3817 NW Expressway, Ste. 950, OKC,OK. 73112 405.949.2221					Wildcat/Bone Spring			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 2310 FSL & 330FWL of Sec. 15-26S-30E				11. Country or Parish, State EDDY, NM				
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICA	TE NATURE (OF NOTIC	E, REPORT OR OTH	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACT				ION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture T	reat	_	oction (Start/Resume)	Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair Change Plans	☐ New Cons☐ Plug and A		=	mplete orarily Abandon	Other	· · · · · · · · · · · · · · · · · · ·	
Final Abandonment Notice	Convert to Injection	Plug Back			r Disposal			
following completion of the involve testing has been completed. Final determined that the site is ready for RIG UP AND SPUD IN 3-11-2010. I 13-3/8" 68# J-55 CASING. LANDER CEMENT W/SCHLUMBERGER AS PUMPED 20BBLS OF WATER FLUPUMPED LEAD: 450SXS OF "C"+4 PUMPED TAIL: 200SXS OF C+1% CIRCULATED 100 SX OF CEMENT WAIT ON CEMENT CUT THE CONTO GET APPROVAL TO CEMENT WELD ON HEAD AND TEST @ 750 RIG UP AND TEST CASING @ 1,00 DRILLED OUT SHOE 29 HOURS A Contacted Bob Hoskinson W/BLM @	Abandonment Notices must In final Inspection) DRILLED 17-1/2" HOLE TO CASING @ 791.6', FLOWS: ISH % D20+.2% D46+1% S1+ S1 + .125 #/SK D130 14.8 TO SURFACE. DUCTOR AND FOUND TO THE TOP WITH REDIMIX D PSI FOR 30 MINUTES. IN ONE OF SIT FOR 10 MINUTES. IN OTHER CEMENT IN PLACE.	o 789'. Ran 18 joi AT COLLAR @ 74 125 #/SK D130, 1 B#/GAL, 1.34 YIEL HE CEMENT HAD AFTER TALKIN NIPPLE UP BOP , TESTED OK.	I requirements, ints (713.55') :6.82'. I2.9#/ GAL, 1. D. DROPPED 8 G WITH THE	of 13-3/8' 97 YIELE 33' (GL). (ENGINEE	reclamation, have been ', 54.5#, J-55, STC C CONTACTED BOB HER, APPROVAL WAS	completed and the ope ASING And 2 Joints	(78.05') of	
			NI IO RUN 8	CM1 CS	il.			
14 I hereby certify that the foregoing is to Gene Simen.	ue and correct Name (Printed	d/Typed)	e Rower	70N <	Superintent	DENT		
Signature June	lmin	Dat	· 3-/5	-10	ACCEPTI	ED FOR RE	CORD	
	THIS SPACE	FOR FEDERA	L OR STA	TE OFF	ICE USE		7	
Approved by			T				T	

Title

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title 18 U S.C. Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any