

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Compromise SWD #1	API Number 30-015-25665	Facility Type Battery
Surface Owner Federal (Bureau of Reclamation)	Mineral Owner Federal	Lease No. NM-65392

LOCATION OF RELEASE



Unit Letter H	Section 30	Township 18S	Range 27E	Feet from the 1980	North/South Line North	Feet from the 800	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.72051 Longitude 104.31146

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20 B/PW	Volume Recovered 12 B/PW
Source of Release Murphy Switch gauge	Date and Hour of Occurrence 8/15/2009 - PM	Date and Hour of Discovery 8/15/2009 - PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Nipple broke on Murphy Switch gauge. Vacuum truck called.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 45'. Pump shut down and repairs made. Vacuum truck recovered remaining produced water. Impacted soils to be scraped up and taken to an NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX, (chlorides will be submitted for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: < 50' (approximately 35'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Signed By  Approved by District Supervisor:	
Printed Name: Robert Asher	MAY 20 2010	
Title: Environmental Regulatory Agent	Approval Date:	Expiration Date:
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: Remediation per Under Rules & Guidelines	Attached <input type="checkbox"/>
Date: Friday, August 21, 2009	Phone: 575-748-4217	

* Attach Additional Sheets If Necessary

n MCB 1014047577

2 RP-412