

## API#: 30-015-37692

WELL NAME AND NUMBE	ER Kersey State #4	
LOCATION Section 32, Lot P, T17S, R28E, 360 FSL, 990 FEL, Eddy County		
OPERATOR Lime Rock Resources		
DRILLING CONTRACTOR	United Drilling, Inc.	
•		
		representative of the drilling contractor
	ed well and had conducted devia	tion test and obtained the following
results:		
Degrees @ Depth	Degrees @ Depth	Degrees @ Depth
3/4 @ 976'	Degrees (a) Depart	Degrees (w. Depui
3/4 @ 1482'		
1 @ 1988'		
1 @ 2488'		WE FREE THE TANKS
1 1/4 @ 2993'		
1 @ 3498'		
1 1/4 @ 4039'		
1 1/2 @ 4512'		
1 3/4 @ 5081'		
-		
	1	***************************************
		<del></del>
	-	
	Drilling Contractor-	UNITED DRILLING, INC.
		Hui o
•	Ву:_	Slusa Marciga
		(Luisa Noriega)
	Title:	Assistant Office Manager
Subscribed and	sworn to before me this 28th	lay of Gally, 2010.
$\frac{1}{\sqrt{N}}$ and $\frac{1}{\sqrt{N}}$		
		Carlie Marten.
		Notary Public
		Notary Public Chaves Alw Mexico
My Commission Expires:	: 10/0/17	County State
,	10/8/12	July State