District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Sunta Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003 Submit 2 Copies to appropriate

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action											
MLB/030	833036)			ATOR						
Name of Co	oretion					Contact Robert Asher					
Yates Petroleum Corporation 25575 Address						Telephone No.					
104 S. 4 TH Street						575-748-1471					
Facility Name API Number Superior KJ Federal Com. #1 30-015-22908						Facility Type Battery					
Surface Owner				Mineral Owner Federal			Lease No. NM-144698				
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County											
Unit Letter Section Township Range D 7 20% 29E				Fect from the No		North Feet from the		West Line		Eddy	
Latitude 32,59259 Longitude 104.11856											
NATURE OF RELEASE											
Type of Release						Volume of Release			Volume Recovered		
Condensate Source of Release						Date and Hour of Occurrence			0 B/C Date and Hour of Discovery		
Production tank						2/1/2010, AM 2/1/2010, AM					
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Require						If YES, To Whom? d Mike Bratcher/NMOCD Artesia					
D. Whom?		I NO I NOT KE	quired	Date and Hour							
By Whom? Robert Asher/YPC Environmental						2/1/10 PM (telephone & e-mail)					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
☐ Yes ☑ No N/A If a Watercourse was Impacted, Describe Fully.*											
N/A											
Describe Cause of Problem and Remedial Action Taken.* Hole in bottom of production tank.											
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 45'. No condensate to recover. Production tank to be pulled and vertical/horizontal delineation to determine extent of											
impacted soils. Work plan to be submitted. Depth to Ground Water: 50-99' (approx. 50'), Wellhead Protection Area: No, Distance to Surface											
Water Body: >1000', SITE RANKING IS 10.											
I hereby certi	fy that the i	nformation gi	ven above	is true and compl	ete to ti	ne best of my	knowledge and u	nderstar	nd that purs	uant to NMOCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
Signature: Que Ql.						OIL CONSERVATION DIVISION					
						Approved by Signed Sipervisor 14 Dennier					
Finited Number Robert Assist											
Title: Environmental Regulatory Agent						Approval Date: NOV 0 4 2010 Expiration Date:					
E-mail Address; boba@yatcsp@trpoleun.com						Conditions of Approval:					
			,	—— ,			יים חי	es and	Attached		
Date: Thursda			h <u>one: 575-748-42</u>	17	REMEDIATION per OCD Rules and						
Attach Addit	ional Shee	ts II Necessa		(Guidelines. SUBMIT REMEDIATION 2RD 1/50						
$\frac{PROPOSAL BY:}{2}/2/4/200$										0×111-478	