

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 08 2010

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nmlb1031240514

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 129/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	F.U.N. State #1H	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-37879
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter A	Section 30	Township 26S	Range 28E	Feet from the 800	North/South Line North	Feet from the 330	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32 01.143 Longitude 104 07.132

NATURE OF RELEASE

Type of Release Produced water		Volume of Release 20bbbls	Volume Recovered 20bbbls
Source of Release Water tank		Date and Hour of Occurrence 10/26/2010	Date and Hour of Discovery 10/26/2010 6:00 a.m.
Was Immediate Notice Given? <div><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required</div>		If YES, To Whom?	
By Whom?		Date and Hour	
Was a Watercourse Reached? <div><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</div>		If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The natural gas water pump did not start, causing the water tank to overflow. Had mechanic check pump. Removed valve handle on supply gas valve to prevent accidental adjustment.

Describe Area Affected and Cleanup Action Taken.*

Initially 20bbbls was released from the water tank and we were able to recover all 20bbbls with a vacuum truck. All fluid was contained inside the facility firewall which is lined with 40 mil plastic. Any contaminated gravel has been removed and clean gravel has been added as necessary. We will follow up with a C-141 Final Report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Josh Russo		Approved by District Supervisor: 	
Title: HSE Coordinator		Approval Date: NOV 08 2010	Expiration Date: N/A
E-mail Address: jrusso@conchoresources.com		Conditions of Approval: Submit	Attached <input type="checkbox"/>
Date: 11/03/2010 Phone: 432-212-2399		Final Report C-141	

* Attach Additional Sheets If Necessary

2 RP-465