RECEIVED

NOV **2 2** 2010

Form C-141

Office in accordance

with Rule 116 on back

NMOCD ARTESIA Copies to appropriate

Revised October 10, 2003

Energy Minerals and Natural Resources Oil Conservation Division

State of New Mexico

1220 South St. Francis Dr. Santa Fe, NM 87505

1220 S. St. Francis Dr., Santa Fe, NM 87505 side of form Release Notification and Corrective Action nMLB1032735832 **OPERATOR** Initial Report Final Report Name of Company OGRID Number Contact Yates Petroleum Corporation 25575 Amanda Trujillo Telephone No. Address 104 S. 4TH Street 575-748-1471 **Facility Name** API Number Facility Type Order Number Sosa Federal #2 30-015-26087 Oil well 2RP- 4-R5 Surface Owner Mineral Owner Lease No. NM-44532 Federal Federal 30-015-26247 LOCATION OF RELEASE Feet from the North/South Line Feet from the East/West Line Unit Letter Township Range County Section 480 SOUTH 660 **EDDY** NATURE OF RELEASE Type of Release Volume of Release Volume Recovered OIL & WATER Date and Hour of Occurrence Date and Hour of Discovery Source of Release 11/16/2010 Flowline failure 11/16/2010 AM If YES, To Whom? Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required Mike Bratcher - NMOCD/Artesia Date and Hour By Whom? Amanda Trujillo - Yates Petroleum Corporation 11/16/2010 pm-Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* A plugged flowline pressured up and blew out. Describe Area Affected and Cleanup Action Taken.* An approximate size of 150' x 1" was impacted. The impacted area is located on the south side if the location. Soil from the pooling areas will be

excavated and disposed of at an NMOCD approved facility. Vertical and horizontal relineation samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Chlorides analysis upon request Depth to Ground Water: >100' (approx. 100', per New Mexico Chevron Texaco Trend Map); Wellhead Protection Avan No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Based on site

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

District III

1301 W. Grand Avenue, Artesia, NM 88210

1000 Rio Brazos Road, Aztec, NM 87410

ground water quality and enclosed analytical result.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other

should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by Dishiersch Brison Printed Name: Amanda Trujillo Approval Date: NOV 2 3 2010 **Expiration Date:** Title: Environmental Scientist Conditions of Approval: E-mail Address: atrujillo@yatespetroleum.com Attached [REMEDIATION per OCD Rules and Date: Friday, November 19, 2010 Phone: 575-748-4310 Guidelines. SUBMIT REMEDIATION * Attach Additional Sheets If Necessary

PROPOSAL BY: 12/23/2010

PHOTE: Remediation proposed to be based on delineation of IPH BTEK & Chlorides

PHOTE: No water quality info or analytical data was so builted with this form.