

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

AKMW 1103247021

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #101	Facility Type	SWD

Surface Owner	State	Mineral Owner	Lease No. (AP#) 30-015-26105
---------------	-------	---------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	5	26	28					Eddy

Latitude 32 04.389 Longitude 104 06.431

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	180bbbls	Volume Recovered	130bbbls
Source of Release	Water line	Date and Hour of Occurrence	01/22/2011	Date and Hour of Discovery	01/22/2011 3:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher—OCD		
By Whom?	Josh Russo	Date and Hour	01/24/2011	10:32 a.m.	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Construction crew tied in water transfer pump at the Myox 31 13 to wrong disposal line causing release. The water transfer pump was hooked up to the appropriate line and returned to service.

Describe Area Affected and Cleanup Action Taken.\*

Initially 180bbbls was released from the line and we were able to recover 130bbbls with vacuum trucks. The spill was largely contained on the pad location of the SRO SWD #101 and measured an area of 50' X 80'. Northwest of the location a 3' x 50' stream traveled off of the location and into the pasture. East of the location produced water flowed measuring an area of 4' x 20'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Josh Russo	Approved by District Supervisor:	Mike Bratcher
Title:	HSE Coordinator	Approval Date:	3/3/11
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	02/01/2011	Phone:	432-212-2399
Conditions of Approval:		Attached <input type="checkbox"/>	
Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:			

\* Attach Additional Sheets If Necessary

4/3/11

2 RP. 597