


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NKMW 11088.38071

Name of Company Linn Operating <i>264324</i>		OPERATOR	X Initial Report <input type="checkbox"/> Final Report
Address PO Box 69 Loco Hills, NM 88255		Contact Dennis Potter	
Facility Name H E West B No. 27 (Keel West Water Flood)		Telephone No. 575 206 7673 cell	
		Facility Type Injection Well	
Surface Owner BLM	Mineral Owner	Lease No. NMLC029426B API 30-015-05074 Federal Tracking #11NU034TG	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	4	17S	31E	660'	South Line	1980'	West	Eddy

Latitude 32.8560 Longitude 103.8769

NATURE OF RELEASE

Type of Release Produced Water and Oil	Volume of Release 50bbls Prod Water/25bbls Oil	Volume Recovered 30bbls
Source of Release Injection Line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 17Feb11
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD	
By Whom? Dennis Potter	Date and Hour 17Feb11	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Source of release was determined and action was taken to stop leak. Vac trucks were utilized to extract all free standing liquid from release point and the area of pooling south of release site. Once all free standing liquid was removed, the contractor will perform excavation to remove all surface sludge and contaminated soil to a depth of approximately 1'-2"BGS. Once the initial action has been completed, delineation will take place with soil samples being obtained and analyzed for BTEX, TPH, Chlorides. Lab analysis will be used to formulate a remediation work plan for submission to NMOCD and BLM. Hungry Horse, LLC has been contracted to perform the remediation.		
Describe Area Affected and Cleanup Action Taken.*		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Dennis J. Potter</i>	OIL CONSERVATION DIVISION	
Printed Name: Dennis Potter	Approved by District Supervisor <i>Mike Bratcher</i> Signed By	
Title: Asst. Production Foreman	Approval Date: <i>3/29/11</i>	Expiration Date:
E-mail Address: dpotter@linenergy.com	Conditions of Approval:	
Date: 28Feb11 Phone: 575 206 7673	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

4/29/11

2RP-668