

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*NKMW 1108332831*

<b>OPERATOR</b>		X Initial Report	XX Final Report
Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	Pure Gold B # 17	Facility Type	Well site
Surface Owner	BLM	Mineral Owner	BLM
		Lease No.	30-015-35305

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20	23S	31E					Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produce water and Oil	Volume of Release	130 bbls	Volume Recovered	0
Source of Release	Illegal Dumping	Date and Hour of Occurrence	07/30/2009	Date and Hour of Discovery	07/30/2009
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Eddy Co. SO.		
By Whom?	Dusty Wilson	Date and Hour	07/30/2009		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Sometime during the night of 7/29/09 and 7/30/09 an unknown trucking company backed to the west edge of location and dumped an estimated amount of Produce water and Oil mix into the pasture covering an area approximately 200' long and 30' wide(average). The spill looked to be mostly produce water with a skim of oil. Soil samples were gathered and analyzed. A work plan was agreed upon by NMOCD Representative. Mike Bratcher, to excavate the area to a 1' depth and backfill with clean like soils. This site was remediated to this agreed work plan and closed.

Describe Area Affected and Cleanup Action Taken.\*

Remediated to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dusty L. Wilson		Accepted for record NMOCD	
Title: HES Specialist		Approval Date:	Expiration Date:
E-mail Address: dusty_wilson@oxy.com	Conditions of Approval: <i>Analytical data to be submitted to NMOCD for review</i>		Attached <input type="checkbox"/>
Date: 10/28/2009	Phone: (575) 397-8210		

- Attach Additional Sheets If Necessary

*2RP-656*