Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

OCD-ARTESIA

FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004

ÉAU QF LAND MANAGEMENT

department or agency of the United

5. Lease Serial No.

NM-27279 (SL) & NM-033775 (BHL) 6. If Indian, Allottee or Tribe Name

SUBMIT IN TR	RIPLICATE - Other Instruc	ctions on reverse	side	7. If U	nit or CA	/Agreement, Name an	d/or No.		
✓ ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No.				
2. Name of Operator				Bradl	ey 28 Fe	d Com #1H			
Mewbourne Oil Company 147	744				Well No				
3a. Address		3b. Phone No. (include	area code)	30-01	30-015-38228 -				
PO Box 5270 Hobbs, NM 88	241	575-393-5905		10. Fie	10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec.,		370 393 6905		Santo	Santo Nino Bone Springs				
	-T18S-R30E Unit Letter E (Su	urface)			11. County or Parish, State				
					Eddy County, NM				
12. CHECK API	PROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT	, OR O	THER DATA			
TYPE OF SUBMISSION		TYI	PE OF ACTION		`				
	Acidize	Deepen	Production (Star	t/Resume)		Water Shut-Off			
Notice of Intent	Alter Casing	Fracture Treat	Reclamation			Well Integrity	\$		
Subsequent Report	Casing Repair	New Construction	Recomplete			Other Spud & Cas	ing		
Subsequent Report	Change Plans	Plug and Abandon	Temporarily At	andon					
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal						
3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)									
02/26/11MI & spud 17 1/2" hole #/g w/ 1.34 yd. Plug down @ 6:0 Schematic attached. Drilled out w 03/04/11. TD'ed 12 1/4" hole @ 1	00 pm 02/26/11. Circ 83 sks to p vith 12 1/4" bit.	oit. At 1:30 am on 02/2	28/11, tested casing t	o 1250# 1	for 30 mi	ins, held OK. Chart	&		
w/1.49 yd. Followed w/60 bbls S Class C w/2% CaCl2. Mixed @ 1 WOC. Ran temp survey indicatin w/1.52 yd. And 150 sks Class C v	Seal Bond Plus, followed w/500: 14.8 #/g w/ 1.34 yd. Plug down ng TOC @ 388'. RIH with 1" piw/additives. Mixed @ 14.8#/g v	sks BJ Lite Class C (35 @ 4:15 am 03/04/11. I pe. Tag at 400'. Cmt in w/1.34. Circ 4 sks ceme	5:65:4) w/additives. Did not circ cmt. Sk n 7 stages with 180 s ent to pit. WOC 18	Mixed @ ow rate lix ks Thixac hrs. Teste) 12.5# /g ft pressur d Class H ed BOPE	g w/2.15 yd. Tail w/ re @ 375# @ 2.7 BP I(8:4) Mixed @ 14.6 to 3000# & annular	200 M. 5#/g		
1500#. At 7:15 AM 03/06/11, tested csg to 1500 for 30 mins, held OK. Chart & schematic attached. Drilled-out-with-8-3/4"-bit. Accepted for record - NMOCD 4-18-11						ORD.			
			<u> </u>						
14. I hereby certify that the foregoing Name (PrintedlTyped)	g is true and correct				API	R 2 2011			

Title Hobbs Regulatory

Date 03/17/11

Name

(Printed/Typed) Office

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to a States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. (Continued on next page)

Approved by (Signature)

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Jackie Lathan

Signature

MAN WELDING SERVICES (V.

Company Mr w/	nover		Date 2 - 4 -	7 – 11	
Lease Occided		leson 2H	County Edd	e dem	
Drilling Contractor_					212 4/1-40

Accumulator Function Test - OO&GO#2

To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
 - 1. Open HCR Valve. (If applicable)
 - 2. Close annular.
 - 3. Close all pipe rams.
 - 4. Open one set of the pipe rams to simulate closing the blind ram.
 - 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
 - 6. Record remaining pressure 1300 psi. Test Fails if pressure is lower than required.
 - a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system}
 - 7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
 - a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop 1000 psi. Test fails if pressure drops below minimum.
- Minimum: a.{700 psi for a 1500 psi system}
 b. {900 psi for a 2000 & 3000 psi system}

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time Test fails if it takes over 2 minutes.
- a. {950 psi for a 1500 psi system}
 b. {1200 psi for a 2000 & 3000 psi system}




WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS Lovington, NM • 575-396-4540

INVOICE

3 13025

Compa	ing Ancia Occiona	•		Date	27-1	Start Time <u>5.00</u>	∏ am ∏ni
Lease	Bond/ + 528 Feel.	conti	211			County	
Compa	ny Man					Outry (- 33)	State */
	ad Vendor			Tester_	リーシック		
Drlg. Co	ontractor Acrosom	UT L				Rig # 50	
Tool Pu						1119 # 7 0	<u> </u>
	De <u>C 17</u>			Plug Size 🕖	1	Drill Pipe Size	V -2
Casing	Valve Opened					1/6	
Check Valve 11	RAMS 12 RAMS 13 RAMS 14	26 2 4 4 5 8b	Rote	ating Head	24 × 22 , × 1	19 18	
C====	9 10 7 8	25			21	₩ 20	16
TEST#	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI		REMARKS	
	25,26,6	112	250	3000			
2	1,2,5	10/10	230	3000			
-	3, 4, 5	19/10	250	3200			
4.	10,8.15	19/10	250				
5.	9,7,15	19/10	250	1500			
6	16	0/0	250	3000			
7	17	10/10	250	10,0			
2	18	101	750	320			
9	19	10/10	250	3-			
				3000			
	/	1.10	2				
	A.		27	A CONTRACTOR OF THE PARTY OF TH	And the World Street, when the Street, which the S		
	HR@ //5) HR@					SUB TOTAL /2	-72°
eage	11 a 122 9 42 1					112	



WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS


INVOICE

B 12119

B) N	my Meu Borne		randton, tar		7 / ri		
	Bladley 28 f	cd #2	$\frac{1}{iJ}$	Date	3-6-11	Start Time_2	00 □(am □ pn
	ny Man Dave Berry N	7.00	. ** 1			County Ec	ay State M
	ad Vendor	Jera B	<u> </u>	Tester	TBACK 1	Madin	
	ontractor Post-Fey501			162(6)	17)h	Ria	1_46
	sher Elfon John inclou					·	
Plug Ty	pe C-ZZ		F	lug Size	$H^{\prime\prime}$	Drill Pjpe Size	4/2x0
Casing	Valve Opened				_ Check Valve Ope	and the same	
	NNULAR 15 1700 PIPC RAMS 12 Blind RAMS 13 RAMS 14	26	Rota	ting Head	24 22	19 19 23	
Check Valve 11	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	25, TEST LENGTH	LOW PSI	HIGH PSI	21	20 REMARKS	_16
1.	13,116,25,26	10-10	20	3000			
2	13951,2	10-10	250	3000			
3	13,10,5,34	10-10	20	3000			
4_	12,10 8	10-10	250	3000			
5	15.10.7	10-10	CVS	1500			
6	14	10-10	2.50	3000			
7	16	10-10	210	3000			
8	1/8	10-10	250	3000			
Ç	19	10-10	250	300)			
							
			011	111			
			1/1	150	June .		
0	115100		V 57		The state of the s		011
—	_HR@_//50					SUB TOTAL	2160
0	_HR@ <i>\$00</i>					TAX	118,80
lileage_	110 01.00					TOTAL	2278,80

MASTER PRINTERS 575.396.3661 (10) MOLHINU!

Mileage 110 @ 1.00






WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

<u>. 13</u>

Lovington, NM • 575-396-4540

INVOICE B 13854

Company Mt W Borne Start Time 8'. 00 □ am 🖒 pm County Eddy State MM Company Man Hau Martin Wellhead Vendor Drig. Contractor Parkerson Tool Pusher Don 1 Drill Pipe Size_ 4 1/2 xo Plug Type C- 22 Plug Size Casing Valve Opened Check Valve Open ANNULAR 15 / 500 RAMS 12 Rotating Head RAMS 13 RAMS 14 ITEMS TESTED TEST LENGTH LOW PSI HIGH PSI REMARKS TEST # 20 3000 10-10 10-10 250 3000 3000 200 10-10 10-10 201 3000 10-10 200 1500 10-10 3000 200 10-10 20 300 10-10 27) 3000 HR@ 1150 1150 SUB TOTAL _____ 100 HR@ TAX 100 A Honel Mileage //) () TOTAL



SCARBROUGH, INC.

SPECIALIZING IN NEW AND EXPERIENCED EQUIPMENT.
VALVE AND CHOKE REPAIR

SELIVERY TICKET

=0. EOX 1588

SOLD TO YMHENSON /1272

PHONE (575) 397-1312 FAX (575) 393-0597

OEBS_NEW MEXICO 88241-1588

SHIPPED TO

MATENG ADI	RESSULTATION OF THE PROPERTY O	(\$6°)	740	100 1 4 2
<u>erk Siase</u> Durchese			No. 1	
QUANTITY ORDERED	Control of the Contro	UNIT PI	RICE	AMOUNT
<u> </u>	Hrs LABOR to Fe build air motor on accumulator			
	air motor on accumulator			
Albučia se se se se se	NATE AND THE SECOND COMES AND REPORTED AND THE FOREST STORES. THE SECOND STORES	Ass. Colon	1962 98810 00	THE THE PERSON NAMED IN TH
Property of the rest of the second	Jest: Closed Annular ? Gared HCR IN. 49 500.			11 mg 1986 garanta (1972) 1944 1974 1974 1974 1974 1974 1974 1974
	Jest: Closed ANNUlar ?			
- 1	grand HCR in. 49 500.	100000000000000000000000000000000000000		
	Big 60 air motor kit			1000
	miles round trip			
	是是在1960年的1960年的1960年的1960年的1960年的1960年的1960年的1960年的1960年的1960年的1960年的1960年的1960年的			
SH SHEET	also checked Dr. Mers Kemole			
15 40 40 40 40 40 40 40 40 40 40 40 40 40	all working)			100 State (100 State)
NPOS NA COLLEG				
		90 MAR (1980 A) 1		
		TO	TAL	