

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 27 2010

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-36532

Release Notification and Corrective Action

NMLB/110436673

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Mewbourne Oil	Contact Kelly Smith
Address 7015 Cecil Hobbs, NM 88241	Telephone No. 575-441-4679
Facility Name Quick Draw 15 I #1	Facility Type Pumping Well

Surface Owner Henry Terpening	Mineral Owner Henry Terpening	Lease No. #1
-------------------------------	-------------------------------	--------------

LOCATION OF RELEASE

Unit Letter I	Section 15	Township 20S	Range 25E	Feet from the 1650'	North/South Line South	Feet from the 330'	East/West Line East	County EDDY
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N30 Longitude W104

NATURE OF RELEASE

Type of Release produced fluids oil/water	Volume of Release 2bbl	Volume Recovered 2bbl
Source of Release leaking stuffing box	Date and Hour of Occurrence 1-14-10	Date and Hour of Discovery 1-14-10 10 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Well gas locked and burnt packing in stuffing box. Recovered standing fluid with vac. Truck and excavated contaminated soil with backhoe and transported to CRI.

Describe Area Affected and Cleanup Action Taken.\*

Affected area was cellar and 20' in front of wellhead on caliche pad. Contaminated soil removed. Took soil sample from affected area and sent to Cardinal labs for analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kelly Smith	Signed By  Approved by District Supervisor:	
Title: Production Forman	Approval Date: 4/14/2011	Expiration Date:
E-mail Address: hobeng@mewbourne.com	Conditions of Approval: Remediation per NMOCD Rules & Guidelines	Attached <input type="checkbox"/>
Date: 1-25-10	Phone: 575-441-4679	

\* Attach Additional Sheets If Necessary

DATA ENTRY - closed

JRP-745