


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Vin Email
Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

AMCB 1112327166 OPERATOR XX Initial Report Final Report
Name of Company Oxy Permian LTD. 16696 Contact Dusty Wilson
Address 1017 W. Stanolind Rd Telephone No. (575) 397-8247
Facility Name Sundance Federal CTB Facility Type Production/Gathering
Surface Owner BLM Mineral Owner Shared Lease No.

Sundance Fed #8 LOCATION OF RELEASE
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County
E 4 24S 31E Eddy

30-015-27547 Latitude Longitude

F-5-24s-316 (PER OPERATOR) NATURE OF RELEASE
Type of Release Produce Water Volume of Release 400 bbls water Volume Recovered 395 bbls
Source of Release Transfer pump shaft separated and High level alarms failed Date and Hour of Occurrence 04/06/2011 0800 pm Date and Hour of Discovery same
Was Immediate Notice Given? XX Yes ☐ No Not Required If YES, To Whom? Mike Bratcher, NMOCD and Jim Amos, BLM
By Whom? Dusty Wilson Date and Hour 4/7/2011 0630 pm
Was a Watercourse Reached? ☐ Yes X No If YES, Volume Impacting the Watercourse. n/a

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Transfer pump shaft separated at this site and the high level alarms failed to reach call out. Pump was repaired and alarms reset. This action caused the tanks to run over and 400 bbls of produced water to spill onto the ground. The fluids did stay within the fire walls of the battery and all free standing fluids were recovered via Vac Truck that was in the area at the time of the spill. Remediation efforts continue at this site and will be to NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.*
Will Remediate to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: [Signature] OIL CONSERVATION DIVISION
Printed Name: Dusty L. Wilson Signed By: [Signature]
Title: HES Specialist Approved by District Supervisor:
Approval Date: 5/3/2011 Expiration Date:
E-mail Address: dusty_wilson@oxy.com Conditions of Approval: Attached ☐
Date: 04/27/2011 Phone: (575) 397-8210

• Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 6/3/2011

2RP-770