<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410

Date: 5-3-11

\* Attach Additional Sheets If Necessary

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr.

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

2RP-777

1220 S. St. Fran	cis la., Sanu	a re, NM 8/30	O COLUMN STATE OF THE STATE OF	S	anta I	Fe, NM 875	505	en e enisseemen	the state of the state of the state of the state of	with any case to the the tendence of the tendence	an armeno	side of form	
V genedalja i savoma	4		Rele	ease Notific	catio	n and Co	rrective A	ction		ror - I y ror o'ny Managanana		The second control of the second seco	
nMLB 111	302659	OPERATOR				al Report		Final Repor					
							Contact Kelton Beaird						
							Telephone No. (O) 575-628-4100						
Facility Na	ne Cima	ron 23-1	<del>i</del>		1	Facility Typ	e Oil well with	Batter	<u>y</u>		<del></del>		
Surface Owner BLM Mineral Owner							Lease No. NM-110						
									API #: 3001533410				
The state of the s	- V			LOCA	ATIO	N OF RE	LEASE						
Unit Letter	Section	Township	Range	Feet from the		h/South Line							
0	23	26S	29E		ľ	•				Eddy		p.	
<u> </u>	1 23	203	********					<u> </u>		Ludy			
LatitudeLongitude													
NATURE OF RELEASE													
Type of Release Oil										Recovered 5bbls			
Source of Release Valve							Date and Hour of Occurrence			Date and Hour of Discovery 4-25-11 @ 10:30 am			
Was Immediate Notice Given? If YES, To Whom?													
			Yes 🔲	No 🔯 Not Re	quired						•		
By Whom? Was a Watercourse Reached?							Date and Hour See above						
Was a Water	course Reac		Yes 🛭	If YES, Ve	If YES, Volume Impacting the Watercourse.								
								· · · · ·					
Describe Cause of Problem and Remedial Action Taken.*  Cow kicked open a valve causing the leak    RECEIVED     MAY 0.9 2011     NMOCD ARTESIA													
Describe Area Area Affected sampled. A c	l was inside	the berms ar	ound the E	Battery. A vacuur	n truck	was called to	pick up the remain	ning flui					
regulations al public health should their o	l operators or or the envir perations ha ment. In ac	are required to onment. The ave failed to a ldition, NIVO	report an acceptanc dequately SD accept	d/or file certain re e of a C-141 repo investigate and re	elease of the control	notifications ar he NMOCD mate contaminati	knowledge and un nd perform correct arked as "Final Re on that pose a thre e the operator of r	tive action of the contract of	ons for releases not releases not releases	eases which ieve the oper r, surface wa	may rator iter, l	endanger of liability human health	
Signature:	: Kelton Be	eaird .	<u> </u>	Approved by	Approved by District Supervisor.								
							approval Date: 5/10/2011 Expiration Date:						
E-mail Addre		beaird@oxy.c	om				onditions of Approval:  Attached						
										,	لسب	1	

Remediation per OCD Rules &

**Guidelines. SUBMIT REMEDIATION** 

PROPOSAL NOT LATER THAN: