

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

copy to SF
Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED
NOV 7 1977
B.G.C. ARTESIA OFFICE
NOV 6 1977
U.S. GEOLOGICAL SURVEY MEXICO

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Flag-Redfern Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 23, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
660' FNL & 660' FEL

14. PERMIT NO. _____

15. ELEVATIONS (Show whether DP, RL, SP, etc.)
3536' GL

5. LEASE DESIGNATION AND SERIAL NO.
NM-3282

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal "35"

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Dexter Field

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 35, T12S, R30E

12. COUNTY OR PARISH
Chaves

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <u>Set surface casing & int. csg</u> <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in MorOilCo., Inc. cable tool rig. Spudded 15½" hole at 12:45 P.M., 9-27-77. Drilled to 340'. Ran 10 jts 12-3/4" csg & set at 340'. Drilled 12-1/4" hole to 754'. Ran 19 jts 8-5/8", 20#/ft casing & set at 754'.

RECEIVED

NOV 3 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Sherry Stephenson TITLE Production Clerk DATE 10-28-77

(This space for Federal or State office use)

APPROVED BY Joe S. Lara TITLE ACTING DISTRICT ENGINEER DATE NOV 4 - 1977

CONDITIONS OF APPROVAL, IF ANY: