



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. LC 067132Unit 1**RECEIVED**
JUN 30 1961F. E. C.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 22, 19 61

Well No. Denton A-2 is located 1650 ft. from N line and 330 ft. from W line of sec. 27

<u>SW/4 NW/4 Section 27</u> (1/4 Sec. and Sec. No.)	<u>183</u> (Twp.)	<u>29E</u> (Range)	<u>NMFM</u> (Meridian)
<u>Turkey Track</u> (Field)	<u>Eddy</u> (County or Subdivision)	<u>New Mex 100</u> (State or Territory)	

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

No show of oil, gas or water this well. Mudded hole back to 360'. Set 50' of cement plug. Mudded hole back to 375'. Set 50' cement plug at this point 1/2 in casing and out. Mudded back to surface and set marker in cement. Recovered about 135' of 3 5/8" casing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kersey & CompanyAddress Box 316Artesia, New MexicoBy Harold KerseyTitle Owner

02140449A
100-1-100
11-10-100-100-100