

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY John A. Yates 323 Carper Bldg., Artesai, N. Mex.
(Address)

LEASE Gulf State WELL NO. 1 UNIT B S 8 T 19S R 28E
DATE WORK PERFORMED 7-6-59 POOL Artesia Undesignated

This is a Report of: (Check appropriate block) Results of Test of Casing Shut-off
 Beginning Drilling Operations Remedial Work
 Plugging Other Fracturing

Detailed account of work done, nature and quantity of materials used and results obtained.

**Perforatied 4½" casing from 1947 to 1942 & 1897 to 1894
Fractured through perforations with 600 Bbls Oil , 80,000#
Sand, 500 Gallons Dwell X & 500# Adcmite.
Natural Test 8 gallons in 24 hours. Test after fracture
20 Bbls. in 24 hours.**

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:
DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
		(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name ML Armstrong
Title _____
Date _____

Name Nela Gorder
Position Bookkeeper
Company John A. Yates

OIL CONSERVATION COMMISSION
 ARTESIA DISTRICT OFFICE

No. Copies Received 3

DISTRIBUTION

	NO COPIES DISTRIBUTED
OPERATOR	<u>1</u>
SALES	<u>1</u>
PROPERTY	
STATE	
UNIT	
TRADING	
PRICE	<u>1</u>
NUMBER OF UNITS	