

(Nov. 1934)

Indian Agency

(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces**Lease or permit No. **029390-D**

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT X |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico 2-15-1944Well No. **Little D-1** located **660** ft. from **N** line and **660** ft. from **E** line of sec. **25****Section 25**
(4 Sec. and Sec. No.)**T-18-S**
(Twp.)**R-31-E**
(Range)**NMPM**
(Meridian)**Goulthard Area**
(Field)**Eddy County**
(County or Subdivision)**New Mexico**
(State or Territory)The elevation of the derrick floor above sea level is **3620** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Mud was pumped into the well from bottom of hole (3797') to 3540', and a cement plug of 25 sax placed on top of mud. Attempts were made to pull 7" after shooting, only recovered approximately 1000' of 7". Hole was again mudded to 1000' where a 25 sax cement plug was placed in bottom of 7" casing, we then mudded hole from 1000' to bottom of 10" where we set another 15 sax cement plug. Attempts were made to pull 10" casing and we only recovered 56' of 10" casing after which the hole was cemented to top, set 4" marker as required law. USGS inspections were made on all cement plugs and well has now been plugged and abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company **Fullerton Oil Company**Address **Box H****Hobbs, New Mexico**

GEOLOGICAL SURVEY

RECEIVED

FEB 17 1944

Artesia, New Mexico

By

Title **Division Sup't.**