

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instructions
reverse side)

TE-
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 6019

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Runyan Federal Com

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 17, 19S, R23E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

RECEIVED

2. NAME OF OPERATOR

Mesa Petroleum Co

JUN 23 1978

3. ADDRESS OF OPERATOR

1000 Vaughn Building/Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

O. C. C.
ARTESIA, OFFICE

1980' FNL & 660' FWL of Section 17

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4063' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) 8-5/8" casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drilled 12 1/4" hole to 1700' 6-14-78. Ran 41 jts 8-5/8" 24# K-55 ST&C (1705.95') w/ shoe at 1697'. Float at 1608'. Ran 1 centralizer on shoe joint and basket at 1100'. Cemented with 200 sx FRC followed by 800 sx 50-50 poz followed by 200 sx Class C + 2% cc. Circ 75 sx to surface. PD at 1:00 AM 6-15-78. WOC 7 hrs. Ran temperature survey - top of cement at 210'. Ran 1" tbg to 210' and cmt w/50 sx Class C. Circ est 2-3 sx good cement. WOC a total of 29 hours. Tested casing to 1500 psi - ok. Reduced hole to 7-7/8" and drilled ahead.

RECEIVED

JUN 22 1978

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Wicki Harrison

TITLE

Agent

DATE

6-21-78

(This space for Federal or State office use)

APPROVED BY

Joe J. Lara

TITLE

ACTING DISTRICT ENGINEER

DATE

JUN 22 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

XC: JLF, JWH, MEC, USGS, FILE,