

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

clst
DP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-26467

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Ceniza AGZ Com

1. Type of Well:
OIL WELL GAS WELL OTHER

FEB 22 1991

2. Name of Operator
YATES PETROLEUM CORPORATION

O. C. D.
ARTESIA, OFFICE

8. Well No.
3

3. Address of Operator
105 South 4th St., Artesia, NM 88210

9. Pool name or Wildcat
Undesignated Morrow

4. Well Location
Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line

Section 13 Township 20S Range 24E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3603' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 26" hole 1:30 PM 2-3-91 with Frank's Rathole Service. Set 40' of 20" conductor and cemented to surface with redi-mix. Notified Darrell Moore, NMOCD, Artesia, NM of spud. Resumed drilling 14-3/4" hole 5:00 PM 2-10-91. Lost circulation 140'. Drilling with no returns. Ran 28 joints 9-5/8" 36# J-55 casing set 1214'. Guide shoe set 1214', insert float set 1170'. Cemented w/200 sx "H" + 12% Thixad + 1% CaCl + 10#/sx Gilsonite (yield 1.52, wt 14.6) plus 900 sx "C" Lite + 5#/sx Gilsonite + 2% CaCl2 + 1/2#/sx Celloseal (yield 1.98, wt 12.4). Tailed in with 200 sx "C" + 2% CaCl2 (yield 1.32, wt 14.8). PD 2:13 AM 2-13-91. Bumped plug to 1000 psi, released pressure, held okay. Had no returns and did not circulate cement. Ran Temperature Survey and found TOC 115'. Redi-mix concrete to surface. WOC. Drilled out 12:45 AM 2-14-91. WOC 22 hrs and 30 minutes. Reduced hole to 8-3/4" and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 2-21-91

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY MIKE WILLIAMS DATE FEB 22 1991
APPROVED BY SUPERVISOR, DISTRICT I9 TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: