

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

FEB 23 1994

2. Name of Operator

Devon Energy Corporation (Nevada) ✓

3. Address and Telephone No.

(405) 552-4511

20 north Broadway Suite 1500 Oklahoma City, OK 73102

4. Location of Well (Feetage, Sec., T., R., M., or Survey Description)

2550' FSL & 580' FWL (CORRECTED PLAT LOCATION)
Section 35-T18S-R31E

FORM APPROVED
Budget Bureau No. 1804-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 10190

6. If Indian, Allotment or Tribal Name

NA

7. If Unit or CA, Agreement Designation

East Shugart Unit

8. Well Name and No.

East Shugart Unit #45

9. API Well No.

10. Field and Pool, or Exploratory Area

Shugart (Y-SR-Q-G)

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recombination
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other submittal of new plat with corrected well site
- ☐ Change of Plans
☐ New Construction
☐ New-Stream Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is discontinuously drilled, give substantial locations and measured and true vertical depths for all casings and zones pertinent to this work.)

On 12/29/93, we submitted an APD to drill this newly staked well in our East Shugart Unit in Eddy County, NM. The location on the plat was used as the reference for the APD. The plat incorrectly stated the location of the well as 2250' FSL and 580' FWL. The well is actually staked 2550' FSL. This is the location approved during the onsite inspection performed by the BLM and the location that was arched. Jim Hunt of Pecos Archeological Services also used the incorrect location in his references. He has amended his report and submitted a corrected copy to your office. Enclosed is a signed copy of the corrected plat. Please make the appropriate changes to our APD.

Post ID-1
3-25-94
Amended F.L.S.

RECEIVED
FEB 7 12 27 PM '94
CARTER
AREA

14. I hereby certify that the foregoing is true and correct

Signed Debby O'Donnell

Title Engineering Tech

Date 2/3/94

(This space for Federal or State office use)

Approved by (ORIG. SGD.) RICHARD L. MANUS
Continued approval, if any:

AREA MANAGER

Date FEB 17 1994