





BOP DIAGRAM
3000# WORKING PRESSURE
RAMS OPERATED DAILY

EAST MILLMAN POOL UNIT NO. 5-5
EDDY COUNTY, NEW MEXICO

EXHIBIT NO. 1