

HUSKY OIL COMPANY  
CHECKLIST FOR WELL REHABILITATION

M & M EXCAVATING  
Route 1, Box 223M  
Carlsbad, New Mexico 88220

Re: CALVANI #1  
Section 29, T22S, R27E  
Eddy County, New Mexico

Please check each item in the space provided to indicate that the work has been done. #7 has space for itemizing the surface restoration (seeding, etc.).

- (✓) 1. All pits have been filled and leveled.
- (✓) 2. Rat hole and cellar have been filled and leveled.
- (✓) 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, township and range numbers which have been permanently stenciled or welded on the marker.
- (✓) 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- (✓) 5. The dead men and tie downs have been cut and removed.
- (✓) 6. If a one-well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk and equipment.
- (✓) 7. All disturbed area has been restored according to the surface owner's specifications as follows:

When the checklist has been completed, sign the blank form below, and submit it with your statement to:

Vera Chandler (303) 850-1462  
HUSKY OIL COMPANY  
6060 S. Willow Drive  
Englewood, Colorado 80111

-----

I certify that the above work has been done and is ready for inspection.

3-15-84  
(Date)

David R. Nalley  
(Contractor)