

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

11015 1992

O.C.D.

WELL API NO. 30-015-27020
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3589
7. Lease Name or Unit Agreement Name Pauline ALB State
8. Well No. 5
9. Pool name or Wildcat Wildcat Delaware

**SUNDRY NOTICES AND REPORTS ON WELLBORES**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>23S</u> Range <u>31E</u> NMPM <u>Eddy</u> County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3386' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 26" hole 10:00 AM 11-15-92. Set 40' of 20" conductor and cemented to surface. Notified NMOCD, Artesia, NM, of spud. Resumed drilling 17-1/2" hole 7:00 PM 11-17-92. Ran 12 joints 13-3/8" 54.5# J-55 casing set 504'. Guide shoe set 504', insert float set 466'. Cmt'd w/225 sx PSL "C" w/2% CaCl2 (yield 1.32, wt 14.8). Tailed in w/250 sx "C" w/2% CaCl2, 1/4#/sx Celloseal (yield 1.32, wt 14.8). Plug down 4:00 PM 11-18-92. Bumped plug to 450 psi, held OK. Circulated 166 sacks. NU and tested to 500 psi for 15 minutes. Reduced hole to 11" and resumed drilling. Ran 90 joints 8-5/8" 32# J-55 casing set 4038'. Float shoe set 4038', float collar set 3993'. Cmt'd w/1500 sx PSL "C" w/10%/sx salt/ 1/4#/sx Celloseal (yield 1.85, wt 12.7). Tailed in w/200 sx "C" w/2% CaCl2 (yield 1.32, wt 14.8). PD 3:23 PM 11-23-92. Bumped plug to 1250 psi, OK. Circulated 245 sacks cement. WOC. Drilled out 4:15 11-24-92. WOC 24 hrs and 50 mins. NU and tested to 1000 psi for 15 mins. Reduced hole to 7-7/8" and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 12-14-92

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ DATE DEC 30 1992

CONDITIONS OF APPROVAL, IF ANY: