Disastical Dis	Submit 3 Copies To Appropriate District	State of New Me		Form C-103	
Total District Substitution Su	Office District I	Energy, Minerals and Natural Resources			Revised June 10, 2003
1301 W. Grand Ave., Austics, MM 8210 1220 South St. Francis Dr. Santa Fe, NM 87505 Santa Fe, NM 97505 Sant				WELL API NO.	
1220 South St. Francis Dr. 1220 Softmans Rd., Julie, NM 87410 1220 Softmans Rd., Julie, NM 87410 1220 Softmans Dr., Smile Fe, NM 87505 16. State Oil & Gas Lease No. 1220 Softmans Dr., Smile Fe, NM 87505 17. Julie Research Rese		OH COMCEDIATION DIVISION		30-005-63052	
1200 Solit Barrow Rd, Autac, NM 87410 Santa Fe, NM 87505 Santa Fe,				5. Indicate Type o	f Lease
Darresty					
1. Elevation (Show whether DR, RRB, RT, GR, etc.) 1. Elevation (Show whether DR, RRB, RT, GR, etc.) 1. Elevation (Show whether DR, RRB, RT, GR, etc.) 1. Elevation (Show whether DR, RRB, RT, GR, etc.) 1. Elevation (Show whether DR, RRB, RT, GR, etc.) 1. Start Rabinating and proposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/14 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118". Tested packer to 600% for 40 mins, held ok. Recorded on chart. 1. Elevation bow is true and complete to the best of my knowledge and belief. SIGNATURE. 1. Elephone No. 505-748-1471 Title DATE DATE DATE		Santa Fe, NM 87	7505	6. State Oil & Gas	Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS OO NOT USE THIS FORM FOR PROPOSALS TO DIRECT ON THE PROPERTY OF THE PROPOSALS TO DIRECT ON TH	1220 S. St. Francis Dr., Santa Fe, NM				
GON DOT USE THIS FORM FOR PROPOSALS TO DRILLOR TO DEEPEN OR PLUG BACK TO A DEEPEN OR PLUG BACK TO BE A D	87505			,	V-2982
GON DOT USE THIS FORM FOR PROPOSALS TO DRILLOR TO DEEPEN OR PLUG BACK TO A DEEPEN OR PLUG BACK TO BE A D	SUNDRY NOTICE	ES AND REPORTS ON WELLS		7. Lease Name or	Unit Agreement Name
RECEIVED State S					8
1. Type of Well: Gal Well Other Injection RECEIVED 9. OGRID Number 0.25575		TION FOR PERMIT" (FORM C-101) FC	OR SUCH	Quinc	y AMQ State
Oil Well	1			8. Well Number	
2. Name of Operator 3. Address of Operator 10.5 S. 48 Street, Artesia, NM 88210 QCD-ARTESIA 4. Well Location Unit Letter G : 2310 feet from the North line and 2310 feet from the East line Section 12 Township 88 Range 27E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3938 'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS PLUG AND ABANDONMENT JOHN JOHN JOHN JOHN JOHN JOHN JOHN JOHN		Oder Test estan			9
2. And of Operator 3. Address of Operator 3. Address of Operator 105 S.4 Street, Artesia, NM 88210 OCD-ARTESIA OCD-ARTESIA OCD-ARTESIA Acme San Andres, Southeast		Other Injection	RECEIVED -		
10. Pool name or Wildcat 10. Pool name or Wildcat Acme San Andres, Southeast			, LOCIVED		
10. Pool name or Wildcat Acme San Andres, Southeast			MAR 1 9 2004		
Unit Letter G : 2310 feet from the North line and 2310 feet from the East line			,		
Unit Letter G : 2310 feet from the North line and 2310 feet from the East line Scction 12 Township 8S Range 27E NMPM Chaves County 11. Elevation (Show whether DR. RKB, RT, GR, etc.) 3938'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT TEMPORARILY ABANDON MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: OTHER Mechanical Integrity Test 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 — MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 — Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118". Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart mached.		88210 O	<u>CD-ARTESIA</u>	Acme San	Andres, Southeast
Section 12 Township 8S Range 27E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3938*GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS ALTERING CASING COMMENCE DRILLING OPNS ABANDONMENT CASING TEST AND ABANDONMENT CASING TEST AND ABANDONMENT CASING TEST AND CHEMPHOLD COMPLETION OTHER: Mechanical Integrity Test 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118*. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart cached. Title: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE. DATE	4. Well Location				
Section 12 Township 8S Range 27E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3938*GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS ALTERING CASING COMMENCE DRILLING OPNS ABANDONMENT CASING TEST AND ABANDONMENT CASING TEST AND ABANDONMENT CASING TEST AND CHEMPHOLD COMPLETION OTHER: Mechanical Integrity Test 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118*. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart cached. Title: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE. DATE					!
Section 12 Township 8S Range 27E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3938*GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS ALTERING CASING COMMENCE DRILLING OPNS ABANDONMENT CASING TEST AND ABANDONMENT CASING TEST AND ABANDONMENT CASING TEST AND CHEMPHOLD COMPLETION OTHER: Mechanical Integrity Test 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118*. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart cached. Title: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE. DATE					
11. Elevation (Show whether DR. RKB, RT, GR, etc.) 3938'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Mechanical Integrity Test X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 - MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart stached. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)	Unit Letter G: 231	0 feet from the North	line and 23	feet from the	e East line
11. Elevation (Show whether DR. RKB, RT, GR, etc.) 3938'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Mechanical Integrity Test X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 - MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart stached. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)				 _	
11. Elevation (Show whether DR. RKB, RT, GR, etc.) 3938'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Mechanical Integrity Test X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 - MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118°. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart stached. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)	Section 12	Township 8S Ran	nge 27E	NMPM Chave	es County
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Mechanical Integrity Test X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 - MIRU. Unset packer and POH. Packer mandrel had a hole in it.Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart placed. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE TITLE DATE TITLE DATE		<u> </u>			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT COMPLETION OTHER: Mechanical Integrity Test X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 - MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118". Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart mached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE:		11. Elevation (Show whether DR,	RKB, RT, GR, etc.)		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Mechanical Integrity Test X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 - MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart attached. I hereby certify that the information above is true and coordilete to the best of my knowledge and belief. SIGNATURE: TITLE Regulatory Compliance Supervisor DATE March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)		3938'	GR	A to the second	The second secon
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Mechanical Integrity Test X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 - MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart attached. I hereby certify that the information above is true and coordilete to the best of my knowledge and belief. SIGNATURE: TITLE Regulatory Compliance Supervisor DATE March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)	12. Check Ap	propriate Box to Indicate N	ature of Notice.	Report or Other I	Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER Mechanical Integrity Test X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it. Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart trached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: Time Huerta E-mail address: tinah@ypcnm.com DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)			1	-	
TEMPORARILY ABANDON			I		
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Mechanical Integrity Test 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it.Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart trached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE	TEN ONWINCIMEDIAL WORK	TEOG AND ABANDON	INLINICUIAL WORL	`	ALTERING CASING
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Mechanical Integrity Test I3. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it.Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart trached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE	TEMPORARILY ARANDON	CHANGE PLANS	COMMENCE DRI	LUNG OPNS	
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Mechanical Integrity Test 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it.Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart packed. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)			O THE PARTY OF BRAIN		
OTHER: Mechanical Integrity Test I. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it.Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart trached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY	PULL OR ALTER CASING	MULTIPLE	CASING TEST AN		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it.Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart mached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE		COMPLETION	CEMENT JOB		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 – MIRU. Unset packer and POH. Packer mandrel had a hole in it.Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart mached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE		_			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3/9/04 - MIRU. Unset packer and POH. Packer mandrel had a hole in it.Set RBP and test casing and tubing to 500#, held good for 15 mins. 3/11/04 - Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart packed. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)	OTHER:		OTHER: Mechani	cal Integrity Test	X
mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart dached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor Title: Regulatory Compliance Supervisor Title: DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE	of starting any proposed work	ed operations. (Clearly state all p.). SEE RULE 1103. For Multiple	pertinent details, and le Completions: Att	l give pertinent dates tach wellbore diagra	, including estimated date m of proposed completion
mins. 3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart dached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor Title: Regulatory Compliance Supervisor Title: DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE	2/2/24				
3/11/04 – Set 5-1/2" x 2-3/8" nickel plated ASI with 1.87" on/off at 2118'. Tested packer to 600# for 40 mins, held ok. Recorded on chart. Notified Van Barton prior to test, no witness on location. MIT chart mached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor Title: Regulatory Compliance Supervisor Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE		H. Packer mandrel had a hole in	it.Set RBP and test	casing and tubing to	500#, held good for 15
Chart. Notified Van Barton prior to test, no witness on location. MIT chart trached. I hereby certify that the information above is true and coefficient to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor Title: Regulatory Compliance Supervisor Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE					
Notified Van Barton prior to test, no witness on location. MIT chart trached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE		ated ASI with 1.87" on/off at 211	Tested packer to	o 600# for 40 mins, l	neld ok. Recorded on
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE	chart.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE			>		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE	Notified Van Barton prior to test, no w	itness on location. MIT chart at	ached.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 12, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE DATE					
SIGNATURE:		35			
SIGNATURE:		<u> A</u>			
SIGNATURE:		, e			
SIGNATURE:		୍ୟ			
SIGNATURE:					
Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY	I hereby certify that the information ab	ove is true and complete to the be	est of my knowledge	and belief.	
Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) APPPROVED BY	A · 1	**			
(This space for State use) APPPROVED BY	SIGNATURE:	TITLE: Reg	ulatory Compliance	Supervisor DA	TE: March 12, 2004
(This space for State use) APPPROVED BY)		-		
(This space for State use) APPPROVED BY	Type or print name Tina Huerta	E-mail ac	ddress: tinah@ypcn	ım.com Tele	phone No. 505-748-1471
APPPROVED BYTITLE DATE	(This space for State use)				
	,				
	APPPROVED BY	TITLE		1	DATE
	Conditions of approval, if any:				

