## YATES PETROLEUM CORPORATION CHRONOLOGICAL DRILLING REPORT Chimay "BAO" State #1 Unit E 2-24S-23E Eddy County, New Mexico YATES PETROLEUM CORPORATION

## 30-015-32508

	Location: 1988' FNL & 155' FWL of Section 2-24S-23E,
	Eddy County, New Mexico. API No.:
	Elevation: 4502' GL. PTD: 10,800' Morrow. Drilling
	Contractor:
10-25-02	Wait on One Call. Jim Krogman notified NM One Call at
10 25 02	4:10 PM 10-24-02. Ticket #2002432697. Will be
	notifying Agave.
10-26-28-02	Upgrade existing raod and build small pad for rathole
	machine. Dirt Contractor: Morgan Tools.
10-29-02	Upgrading existing road and build small pad for rathole
+ ,	machine.
10-30-02	Stand by. Ungraded existing road and built small pad
10 1 00	for rathole machine.
10-1-02	Stand by
11-1-02	Prep to spud with Butch's Rathole.
11-2-02	TD 10'. Stand by. Spudded with Butch's Rathole
11 2 02	Service at 10:30 AM 11-1-02. Hole size 12.25".
	Notified Van Barton with Artesia OCD.
	Notified van Barton with Mitchia OCD.
11-5-02	TD 10'. Stand by.
11-6-02	TD 10'. Stand by.
11-7-02	TD 10'. Stand by.
11-22-02	TD 10'. Stand by. Prep to make 5' of new hole with
	Butch's Rathole. NOTE: New One Call ticket
	#2002471856.
11-22-02	TD 15'. Stand by. Made 5' of new hole at 9:30 AM 11-
	21-02 with Butch's Rathole. Hole size 12.25".
11 00 04 00	Notified Tim Gunn with Artesia OCD via voice mail.
11-23-24-02	TD 15'. Wait on One Call.
11-25-02	TD:15'. Prep to build location.
11-26-02 11-27-02	TD 15'. Building location. TD 15'. Building location.
11-28/12-2-02	
12-3-02	TD 15'. Building location. New One Call ticket
12-3-02	#2002471856. Notified Tim Gunn with Artesia OCD via
	voice mail. Building location with Jim Wilson
	Construction.
12-4-02	TD 15'. Building location with Jim Wilson
	Construction.
12-5-02	TD 15'. Building location with Jim Wilson
	Construction.
12-6-02	TD 15'. Building location.
12-7-9-02	TD 15'. Building location.
12-10-02	TD 15'. Building location with Jim Wilson
	Construction.
12-11-02	TD 15'. Building location. Prep to make 5' of new
10 10 00	hole with Butch's Rathole.
12-18-02	TD 20'. Building location with Jim Wilson
12 10 02	Construction.
12-19-02 12-20-02	TD 20'. Building location with Jim Wilson. TD 20'. Building location with Jim Wilson
12-20-02	Construction.
12-21-23-02	Building location with Jim Wilson Construction.
12-24-02	Building location with Jim Wilson Construction.
<del></del>	

```
DR
Page 2:
Yates Petroleum - Chimay "BAO" State #1 (Unit E) 2-24S-23E
Building location with Jim Wilson Construction.
                    down for Christmas.
12-26-02
                    Building location with Jim Wilson Construction.
                    Building location with Jim Wilson Construction. Building location with Jim Wilson Construction.
12-27-02
12-28-30-02
                    TD 20'. Building location. Prep to make 5' of new hole with Butch's Rathole Service.
12-31-02
                    TD 25'. Building location. Made 5' of new hole with
1-1-03
                    Butch's Rathole Service. Hole size 12.25". Notified
                    Van Barton with Artesia OCD via voice mail.
                    TD 25'. Building location.
1-2-03
1-3-02
                    TD 25'. Location finished.
                                                          Stand by.
                    TD 25'. Standby.
1-4-6-03
1-7-03
                    TD 25'. Stand by.
                    TD 25'. Stand by.
1-8-03
1-9-03
                    TD 25'. Prep to set condcutor. Moving in Butch's
                    Rathole to set conductor pipe.
                    TD 40'. Moving in rotary tools. Moved in Butch's Rathole and set 40' of 20" conductor pipe. Notified Van Barton with OCD of continious operations.
1-10-03
                    TD 40'. Rigging up rotary tools and prep to resume
1-11-03
                    drilling.
                    Drilling 320' surface. Made 280' in 18-1/4 hours,
1-12-03
                    15.34'/hr. Mw 8.4, Vis 29. WOB all, RPM 90, SPM 85,
                    PP 350#. Rigging up rotary tools and prep to resume drilling. Resumed drilling at 11:00 AM 1-11-03.
                    Drilled to 233'. Lost returns at 230'. Mixed and
                    pumped LCM sweep - no returns. Survey 190' 1/2 deg. Drilled to 320'. DC $111,411; CC $111,411
                    TD 389' anhydrite. 1" cement. Made 69' in 4 hours, 17.25'/hr. MW 8.4, Vis 28. WOB all, RPM 90, SPM 85, PP 350#. Drilled to 360'. Rig service. Drilled to 389'. TD 17-1/2" hole at 10:15 AM 1-12-03. Pumped
1-13-03
                    sweep and circulate. Survey 346' 2 deg. TOH to run
                    13-3/8" casing. Rigged up casing crew and run 9 joints 13-3/8" 48# H-40 (391.09') casing, set at 389'. Texas
                    Pattern guide shoe set at 389'. Float collar set at
                    345.53'. Rigged up BJ Services and circulated. Pumped
                    200 sacks Class "H" (A-10) with 2% CaCl2 + .25#/sx
                    Celloflake + 10#/sx LCM-1 (yld 1.52, wt 14.6). Tailed
                    in with 425 sacks Class "C" ^- + 2% CaCl2 (yld 1.34, wt
                    14.8). PD at 4:45 PM 1-12-03. Bumped plug to 225#, held OK. Did not circulate cement. WOC. Cut off conductor and 13-3/8" casing. Rigged up Temp. survey
                    (tool not working - received verbal permission from
                    Gerry Guy with OCD to just 1" cement). Ran 1". Tagged
                    cement initially at 230'. DETAILED 1" REPORT TO
                    FOLLOW. DC $23,623; CC $135,034
1-14-03
                    Drilling 520' anhydrite. Made 131' in 13-1/4 hours, 9.89'/hr. MW 8.4, Vis 28, pH 10. WOB 25,000, RPM 70,
                    SPM 110, PP 700#. Finished 1" cementing as follows:
                    Ran 1". TAgged cement at 235'. Spotted 50 sacks Class
                    "C" + 4% CaCl2. Stopped pumping at 11:30 PM 1-12-03.
WOC 1 hour. Ran 1". Tagged cement at 230'. Spotted
25 sacks Class "C" + 4% CaCl2. Stopped pumping at 1:00
AM 1-13-03. WOC 1 hour. Ran 1". Tagged cement at
192'. Spotted 25 sacks of Class "C" + 4% CaCl2.
Stopped pumping at 2:30 AM 1-13-03. WOC 1 hour. Ran
1" Tagged coment at 192'. Spotted 25 sacks Class "C"
                    1". Tagged cement at 192'. Spotted 25 sacks Class "C"
                    + 4% CaCl2. Stopped pumping at 4:00 AM 1-13-03. WOC 1
                    hour. Ran 1". TAgged cement at 192'. Spotted 25
                    sacks Class "C" + 4% CaCl2. Stopped pumping at 5:45 AM
```

1-13-03. WOC 1 hour. Ran 1". Tagged cement at 169'. Spotted 50 sacks Class "C" + 4% CaCl2. Stopped pumping at 7:15 AM 1-13-03. WOC 3-1/2 hours. Ran 1". Tagged cement ta 99'. Spotted 100 sacks Class "C" + 4% CaCl2. Stopped pumping at 11:00 AM 1-13-03. Circulated 10

Page 3:

Yates Petroleum - Chimay "BAO" State #1 (Unit E) 2-24S-23E \*\*\*\*\*\* sacks to pit. Welded on rotating head flange. Hooked up rotating head and hooked up flowline. TIH and tagged cement at 328'. Drilled cement, plug and float. Drilled out at 4:45 PM 1-13-03. WOC 24 hours. Reduced hole to 7-7/8" and resumed drilling. Drilled to 520'. DC \$22,076; CC \$157,110 Drilling 840' anhydrite. Made 320' in 20-1/4 hours, 10.70'/hr. MW 8.4, Vis 28, pH 10.5. WOB 35,000, RPM 1-15-03 70, SPM 100, PP 725#. Drilled to 544'. Rig service. Survey 501' 1-1/2 deg. Drilled to 699'. Survey 657' 1-1/4 deg. Drilled to 840'. DC \$8140; CC \$165,250 Drilling 1310'. Made 470' in 22 hours, 21.36'/hr. MW 1-16-03 8.4, Vis 28. WOB 45,000, RPM 70, SPM 70, PP 400#. Rig service. Survey 812' 3/4 deg. Drilled to 1007'. Survey 965' 1-1/4 deg. Drilled to 1164'. Survey 1122' 1-1/4 deg. Drilled to 1213'. Lost returns at 1213'. Mixed and pumped LCM sweeps. Did not regain returns. Drilled to 1310'. Drilling with no returns. DC \$9014; CC \$174,264 Drilling 1825'. Made 515' in 23-1/4 hours, 22.15'/hr. 1-17-03 MW 8.4, Vis 28. WOB 50,000, RPM 70, SPM 70, PP 300#. Drilled to 1419'. Rig service. Survey 1376' 3/4 deg. Drilled to 1674'. Survey 1631' 1/2 deg. Drilled to 1825'. DC \$17,418; CC \$191,682 TD 1970' limestone. TIH with bit #3. Made 145' in 12-1/4 hours, 11.84'/hr. MW 8.4, Vis 28, pH 8. WOB 50, 1-18-03 RPM 60/70, SPM 70, PP 350#. Drilled to 1895'. Service rig. Drilled to 1927'. Survey 1885' 3/4 deg. Drilled to 1970'. TOH to change out rotary table. Changed out rotary table. TIH with bit #3. Drilling with no reutrns. DC \$14,832; CC \$206,514 Drilling 2402' lime. Made 432' in 21 hours, 20.57'/hr. MW 8.4, Vis 28, pH 8. Drilling wiht no returns. WOB 50, RPM 65, SPM 70, PP 400#. Finished TIH. Reamed 60' to bottom. Drilled to 2023'. Service rig. Drilled to 2180'. Survey 2137' 3/4 deg. Drilled to 2402'. Fluid 1-19-03 level approx 60'. DC \$20,052; CC \$226,566
TD 2515' lime. 1" cementing. Made 113' in 5-1/4 1-20-03 hours, 21.52'/hr. MW 8.4, Vis 28, pH 8. WOB 50, RPM 65, SPM 70, PP 450#. Drilled to 2515'. TD 12-1/4" hole at 11:15 AM 1-19-03. Pumped viscous sweep. Dropped totco and TOH with bit #3. Rigged up lay down machine and laid down drill collars. Rigged up casers and run 58 joints 9-5/8"36# J-55 (2517.63') casing, set at 2515'. Rigged up BJ and circulated. Cemented with 200 sacks "H" + 10% H-10 + 1% Cacl2 + 10# LCM-1 + 1/4# celloflake and 600 sacks 35:65:6 "C" + 5# salt + 5# LCM-1. Tailed in with 200 sacks "C" + 1% CaCl2. PD at 8:45 PM MST 1-19-03. Cement did not circultae. WOC. Cut off conductor pipe and casing. Run temperature survey and found TOC at 1270'. Run 1" - tagged cement at 1269'. DETAILED CASING REPORT TO FOLLOW. \$48,962; CC \$275,528 TD 2515' lime. Test BOP. Made 0'. MW 8.4, Vis 28. 1-21-03 1" cementing - circulated 10 sacks to pit on 6th stage. WOC. Cut off casing and weld on head. Tested head to 1000#, OK. Nippled up BOP and choke manifold. Tested BOP and choke manifold to 5000# (low pressure test to 250#). Tested annular to 2500#. DC \$34,839; CC \$310,367 DETAILED CASING REPORT: Ran 58 joints 9-5/8" 36# J-55 ST&C (2517.63') casing, set at 2515'. Texas Pattern Guide shoe set at 2515'. Float collar set at 2472'. Cemented with 200 sacks "H" + 10% A-1 + 1% CaCl2 + 10# LCM-1 + 1/4# Celloflake (yld 1.52, wt 14.6) and 600 sacks 35:65:6 "C" + 5# salt + 5# LCM-1 (yld 2.03, wt 12.5). Tailed in with 200 sacks "C" + 1% CaCl2 (yld

Page 4:

Yates Petroleum - Chimay "BAO" State #1 (Unit E) 2-24S-23E \*\*\*\*\*\*\*Eddy Co., NM\*\*\*\* 1.34, wt 14.8). PD at 8:45 PM 1-19-03. Bumped plut to 1150#, held OK. Cement did not circulate. WOC 5 hours. Ran temperature survey and found TOC at 1270'. Ran 1". Tagged cement at 1269'. Spotted 50 sacks Class "C" + 4% CaCl2. Stopped pumping at 6:30 AM 12-20-03. WOC 1-1/2 hours. Ran 1". Tagged cement at 1252'. Spotted 25 sacks Class "C" + 4% CaCl2. Stopped pumping at 8:15 AM 1-20-03. WOC 1-1/2 hours. Run 1". Tagged cement at 1252'. Spotted 25 sacks Class "C" + 4% CaCl2. Stopped pumping at 10:15 AM 1-20-03. WOC 1-1/2 hours. Ran 1". Tagged cement at 1252'. Spotted 25 sacks of Class "C" + 4% CaCl2. Stopped pumping at 12:15 AM 1-20-03. WOC 1-1/2 hours. Ran 1". TAgged cement at 1142'. Spotted 100 sacks Class "C" + 4% CaCl2. Stopped pumping at 2:15 PM 1-20-03. WOC 1-1/2 hours. Ran 1". Tagged cement at 667'. Spotted 225 sacks Class "C" + 2% CaCl2. Stopped pumping at 4:30 PM 1-20-03. Circulated 10 sacks cement to pit. NOTE: Ran centralizers on joints #1, 4, 7, 10 and 13. Did not circulate cement on initial cement job.

Drilling 2975' lime and sand. Made 460' in 10-3/4 hours, 42.79'/hr. MW 8.8, Vis 28, pH 10.5. BGG 5.

WOB 60,000, RPM 60, SPM 100, PP 1300#. Rig repair - replaced hook on blocks. Picked up BHA and TIH. 1-22-03 Drilled cement, plug and float. Drilled out at 7:00 PM 1-21-03. WOC 46 hours 15 mins. Reduced hole to 8-3/4" and resumed drilling. Drilled to 2785'. Survey 2785' 1 deg. Drilled to 2975'. DC \$15,108; CC \$325,475 Drilling 3805' dolomite. Made 830' in 23 hours, 1-23-03 36.09'/hr. MW 8.9, Vis 29, pH 10.5. BGG 10. WOB 60,000, RPM 60, SPM 100, PP 1350#. Drilled to 3260'. Rig service. Survey 3215' 3/4 deg. Drilled to 3736'. Survey 3691' 1-1/4 deg. Drilled to 3805'. NOTE: Losing fliud at 3200'. Went thru steel pits and lost 20 bbls in 1 hour. Pumped paper sweeps - no losing any fluid at report time. DC \$10,268; CC \$335,743 Drilling 4395' lime, sand and shale. Made 590' in 23-1-24-03 1/4 hours, 25.38'/hr. MW 8.9, Vis 28, pH 10.5. BGG 10. WOB 55,000#, RPM 60, SPM 100, PP 1350#. Drilled to 4022'. Rig service. Drilled to 4212'. Survey 4167' 1-3/4 deg. Drilled to 4395'. DC \$8672; CC \$344,415 1-25-03 Drilling 4790' lime, shale and sand. Made 395' in 22-3/4 hours, 17.36'/hr. MW 8.9, Vis 28, pH 10.5. BGG 20. WOB 55,000, RPM 60, SPM 100, PP 1400#. Drilled to 4433'. Rig service. Survey 4388' 2 deg. Drilled to 4687'. Survey 4642' 2 deg. Drilled to 4790'. DC \$15,140; CC \$359,555 1-26-03 Drilling 5100' lime and shale. Made 310' in 22-3/4 hours, 13.63'/hr. MW 8.9, Vis 28, pH 10.5. BGG 10. WOB 50,000, RPM 60, SPM 100, PP 1400#. Drilled to 4877'. Rig service. Drilled to 4941'. Survey at 4896' misrun. Drilled to 4945'. Survey 4928' 2-1/2 deg. Drilled to 5100'. DC \$8890; CC \$368,445 Drilling 5270' lime, sand and shale. Made 170' in 22-1/2 hours, 7.56'/hr. MW 8.9+, Vis 28, pH 10.5. BGG 1-27-03 10. WOB 40,000, RPM 60, SPM 100, PP 1450#. Rig service. Survey 5055' 3-1/2 deg. Drilled to 5195'. Survey 5150' 3-1/4 deg. Drilled to 5270'. DC \$8890 DC \$8890; CC \$377,335 Drilling 5500' lime and shale. Made 230' in 15-3/4 1-28-03 hours, 14.60'/hr. MW 9, Vis 28, pH 10.5. BGG 5, TG 50. WOB 35, RPM 40/95, SPM 105, PP 1300#. Drilled to 5290'. Rig service. Survey 5245' 3-1/4 deg. Drilled to 5300'. TOH with bit #4. Picked up bit #5, motor, reamer and TIH. Washed 55' to bottom, no fill. Drilled to 5415'. Survey 5349' 3 deg. Drilled to