

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-22621

Release Notification and Corrective Action

NMLB 1121329960

3080

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company	Burnett Oil Co. Inc.	Contact	Balton Mathews
Address	Box 199 Loco Hills NM 88255	Telephone No.	575-677-2313
Facility Name	Jackson B # 32	Facility Type	Ing. Well
Surface Owner	BLM	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	1	17	30	1980	South	1980	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Salt Water	Volume of Release	Apr. 2006	Volume Recovered	306Lg
Source of Release	Casing Leak	Date and Hour of Occurrence	7/4	Date and Hour of Discovery	7/5 9am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bradshaw - OED Jim Ayres - BLM		
By Whom?	Eddie Seay - Agent	Date and Hour	7/5 9:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED  
JUL 11 2011  
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\*

Hole in casing causing injection water to come to surface, and into pasture  
shot in injection, vacuum up water, build emergency pit to catch water,  
also put back tank to hold water. Waiting on Pulling unit to repair well.

Describe Area Affected and Cleanup Action Taken.\*

Ran into pasture south & west; water pooled up in low spot approx 125 ft  
south. area (110x80) water soaked. Ran out in small drain, 2x4 ft wide  
approx 150 ft. All available water vacuumed up. (will file Work Plan for remediation)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Eddie W Seay		
Title:	Agent		
E-mail Address:	seay@blm.gov		
Date:	7/3/2011	Phone:	575-390-2454
Approved by District Supervisor:		Signed By: Mike Bradshaw	
Approval Date:		8/1/2011	Expiration Date:
Conditions of Approval:		Attached <input type="checkbox"/>	

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:  
Remediation Proposal  
Rec'd 7/14/2011

2 RP-803