


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nmcb1121351343

229137

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #102	Facility Type	Salt Water Disposal

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-21398
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	26S	28E					Eddy

Latitude 32 02.649 Longitude 104 05.441

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	19bbls
Source of Release	Produced water tank	Date and Hour of Occurrence	06/16/2011	Date and Hour of Discovery	06/16/2011 12:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Due to maintenance at the other disposals, this disposal was receiving more water than normal causing the release.

Describe Area Affected and Cleanup Action Taken.*

Initially 20bbls of produced water was released from the produced water tank inside the dike walls of the SRO SWD #102. We were able to recover 19bbls of water with a vacuum truck and the entire release was contained inside the lined facility. All free fluid has been removed; the facility has been washed/cleaned and returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Josh Russo	OIL CONSERVATION DIVISION	
Title:	HSE Coordinator	Approval Date:	8/1/2011
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	NA
Date:	07/01/2011	Phone:	432-212-2399
		Conditions of Approval:	NA
		Approved as Final Report	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-804