

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

NMLB 1121540352

255333

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company : LIME ROCK RESOURCES II-A, L.P	Contact : Jerry Smith
Address : 1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No. : 575-748-9724
Facility Name : AID 24 State Produced Water Transfer Line	Facility Type: Produced Water Transfer Line

Surface Owner : State	Mineral Owner	Lease No. : API #30-015-22878
-----------------------	---------------	-------------------------------

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	17S	28E	900	FSL	990	FWL	Eddy

**Latitude** 32.80140 **Longitude** -104.152254

**NATURE OF RELEASE**

Type of Release : Produce Water	Volume of Release : 40 bbls	Volume Recovered: 10
Source of Release : Poly Line	Date and Hour of Occurrence: 7/21/11 10:00 am	Date and Hour of Discovery: 7/21/11 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD/Mike Bratcher by voicemail	
By Whom? Mike Stubblefield	Date and Hour : 7/21/11 1:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\* A connection in a new 4" poly line parted causing the release. The line was isolated and a vacuum truck was immediately brought to location. All free standing fluids were recovered.

Describe Area Affected and Cleanup Action Taken.\*

The initial release area was south of Apache Corp. D State #5 (30-015-31422) location, measuring approximately 89' long by 23' wide. The release then flowed onto the Apache Corp D State #5 location measuring approximately 324' long by 62' wide. A small area located west of the location was also affected. This area measured approximately 21' long by 7' wide. Talon/LPE was contracted for the correction of this release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jerry Smith	Signed By Approved by District Supervisor:	
Title: Assistant Production Supervisor	Approval Date: <u>8/3/2011</u>	Expiration Date:
E-mail Address: jsmith@limerockresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/01/11 Phone: 575-748-9724	Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b> <u>9/3/2011</u>	

\* Attach Additional Sheets If Necessary

2RP-809