

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-36923

Release Notification and Corrective Action

nmlb 1118837272

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Banjo BNO Federal #1	API Number 30-015-36923	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-102034
--------------------------	--------------------------	------------------------

LOCATION OF RELEASE

Unit Letter P	Section 5	Township 26S	Range 30E	Feet from the 510'	North/South Line South	Feet from the 330'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.06576 Longitude 103.89553

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 130 B/PW	Volume Recovered 130 B/PW
Source of Release Discharge hose on water pump	Date and Hour of Occurrence 6/23/2011; AM	Date and Hour of Discovery 6/23/2011; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/23/2011, PM (voicemail); 6/23/2011, PM (email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

A discharge hose on the water pump blew. The pump was turned off and a vacuum truck and roustabout crew were called to the location.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 210' X 27' (all released water was contained in lined/bermed battery). The discharge hose on water pump was repaired, and all produced water was recovered. **Depth to Ground Water: >100' (approximately 173', Section 5, T26S-R30E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on battery being lined/bermed and all water recovered, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon	Approved by District Supervisor Signed By <i>Mike Bratcher</i>	
Title: Environmental Regulatory Agent Trainee	Approval Date: <i>7/7/2011</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>acannon@yatespetroleum.com</i>	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: Thursday, June 30, 2011 Phone: 575-748-4111	2RP-802 <i>Final</i>	

* Attach Additional Sheets If Necessary

2RP-802