

Received 9/18/2014

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: OXY USA WTP Limited Partnership	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: PIGLET 21 CTB	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No.: Lease #: 30-015-39371
-----------------------------	----------------	---------------------------------------

LOCATION OF RELEASE

Unit Letter I	Section 21	Township 17S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	---------------------

Latitude **32.8172087 N** Longitude **-104.173429 W**

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30 bbls PW	Volume Recovered: -0- bbls PW
Source of Release: Human Error Load line not disconnected	Date and Hour of Occurrence 5/16/14 @ 9:00 am	Date and Hour of Discovery 5/63/14 @ 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher @ NMOCD - email Jennifer Van Curen @ BLM - email	
By Whom? Chris Jones	Date and Hour: 5/16/2014 12:44 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A driver drove off without disconnecting his load line which caused 30 barrels of produced water to be released. No fluids were recovered. Talon/LPE was contracted to perform an initial site assessment and soil sampling.

Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 300' x 35'. This release occurred on location and flowed west off location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist:	
Title: HES Specialist	Approval Date: 9/23/2014	Expiration Date: NA
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/19/2014 Phone: 575-628-4121		

* Attach Additional Sheets If Necessary

2RP-2510