

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

RECEIVED
FEB 14 2013
Initial Report
NMOCD ARTESIA

OPERATOR

Final Report

Name of Company BOPCO, L.P.	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Golden 8 Federal Battery #1 (2RP-466)	Facility Type E&P

Surface Owner: Federal	Mineral Owner: Federal	Lease No.
------------------------	------------------------	-----------

LOCATION OF RELEASE

30-015-26931

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	8	21S	29E					Eddy

Latitude N32.491352 Longitude W104.008223

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release 10 bbls Crude oil	Volume Recovered None
Source of Release: 2 7/8" flow line near tank battery	Date and Hour of Occurrence Not known	Date and Hour of Discovery 10/6/10 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour: 3/10/10 7:00 a.m. Left Msg. Returned call later	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken: A 2 7/8" flow line developed a leak coming from the producing well to the battery. The well was shut in and one joint of tubing was replaced.

Describe Area Affected and Cleanup Action Taken.* An area covering approximately 1,600 sq. ft. of pasture near the south side of the tank battery to the lease road was affected by the release. The oil soaked area was covered with fresh dirt to absorb the pockets of oil.

Laboratory analytical results from soil samples collected from the floor and sidewalls of the Golden 8 Federal Battery #1 Flowline excavation indicated concentrations of BTEX, TPH and chloride were less than NMOCD regulatory standards. Approximately 432 cy of impacted soil was excavated from the release site. Affected soil was transported to an NMOCD-approved disposal facility. On April 24, 2012, the excavation was backfilled with locally purchased non-impacted soil.

Please reference the attached Basin Environmental Services Technologies Remediation Summary and Site Closure Request for details of remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: ASST Len J. Arguizo (Asst. of BOPCO, LP)	Approved by District Supervisor: 	
Title: ASST Project Manager - Basin Environmental	Approval Date: 1/16/15	Expiration Date: NA
E-mail Address: TASavoie@BassPet.com pm@basinenv.com	Conditions of Approval: Final	
Date: 2/14/15	Phone: 432-556-8730	

(806)549-9597

2RP-466