

Rec'd 12/19/14
NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Robert McNeil
Address	600 West Illinois Avenue, Midland, Texas 79701	Telephone No.	(432) 230-0077
Facility Name	GJ West Coop Unit South Water Distribution Site	Facility Type	Injection Line

Surface Owner: State	Mineral Owner	Lease No.	30-015-10756
----------------------	---------------	-----------	--------------

LOCATION OF RELEASE

Tracking: 30-015-35777

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	28	17S	29E					Eddy

Latitude N 32 48.655 Longitude W 104 04.555

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release	100 bbls	Volume Recovered	50 bbls	
Source of Release	Nipple off of injection line 90	Date and Hour of Occurrence	09-17-2010	Date and Hour of Discovery	09-17-2010 2:00p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Josh Russo	Date and Hour	09-17-2010 5:57 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A


Describe Cause of Problem and Remedial Action Taken.*

A nipple came loose off of the 90 on the injection line. All old fittings were replaced with new fittings

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech inspected site and collected samples to define spills extent. Selected areas with soils that exceeded RRAL were removed and hauled away for proper disposal if accessible. Liners were installed according to the work plan. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez		Approved by District Supervisor:	
Title: Project Manager, P.G.		Approval Date: 3/9/15	Expiration Date: N/A
E-mail Address: ike.tavarez@tetratech.com		Conditions of Approval: FINAL	
Date: 12/11/14 Phone: (432) 687-8110		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-462