

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Avenue, Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised October 10, 2003

Submit 2 Copies to appropriate  
 District Office in accordance  
 with Rule 116 on back  
 side of form

**Release Notification and Corrective Action**

nJMW1316839427

**OPERATOR**

Initial Report  Final Report

Name of Company <u>Linn Operating</u>	Contact <u>EL Gonzales</u>
Address <u>2130 W Bender Hobbs NM 88240</u>	Telephone No. <u>575-738-1739</u>
Facility Name <u>J L Keel B #84</u>	Facility Type <u>Oil Producer</u>

Surface Owner <u>Federal</u>	Mineral Owner <u>Federal</u>	Lease No. <u>3001528551</u>
------------------------------	------------------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	05	17S	31E	2598	North	1293	East	Eddy

Latitude 32.86356 Longitude -103.88978

**NATURE OF RELEASE**


Type of Release <u>Produced Water/ Oil</u>	Volume of Release <u>20 bbls/1bbs</u>	Volume Recovered <u>0/0</u>
Source of Release <u>3" Polly line</u>	Date and Hour of Occurrence <u>6/3/13</u>	Date and Hour of Discovery <u>6/3/13</u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>M. Bratcher NMOCD</u>	
By Whom? <u>Gary Wink</u>	Date and Hour <u>6/6/2013 09:00</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* While running route I noticed that there was a black spot out in pasture. Drove to location and found 3" polly line that was leaking.

Describe Area Affected and Cleanup Action Taken.\* DFSI blended and tilled the affected area. Re-seeded with BLM LPC seed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <u>EL Gonzales</u>	Approved by District Supervisor: <u>M Bratcher</u>	
Title: <u>Production Supervisor</u>	Approval Date: <u>3/18/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>elgonzales@linenergy.com</u>	Conditions of Approval: <u>N/A</u>	Attached <input type="checkbox"/>
Date: <u>2/16/2016</u> Phone: <u>575-504-8002</u>	<b>FINAL</b>	

\* Attach Additional Sheets If Necessary

2RP-1683