Received 1/26/2017 NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB16019272	284				OPERATOR				ial Report	X	Final Report		
Name of Co			7 x p 2 x 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		Contact: Johnny Titsworth								
			ort Worth, TX 76102		Telephone No. (432) 425-2891								
Facility Name: Jackson A 2 Facility Type: Tank Battery													
Surface Own	ner: BLM	[Mineral C	wner: E	BLM			API No. <mark>30-015-37494</mark>					
				LOCA	TION	OF RE	LEASE						
Unit Letter O	Section Township Range Feet from the North 12 17S 30E 1115 FSL				Company and the Company	South Line	Feet from the 2210	East/West Line FEL		County Eddy			
Latitude: 32.84491 Longitude: -103.92381													
NATURE OF RELEASE													
Type of Relea						Recovered 25 bbls							
Source of Release: poly pipe							Date and Hour of Occurrence: 1/11/16			Date and Hour of Discovery: 1/11/16 10:00 am			
Was Immediate Notice Given? X Yes ☐ No ☐ Not Required						If YES, To Whom? OCD - H. Patterson BLM – S. Tucker							
By Whom? L	eslie Garvi			Date and Hour: 1/12/16 3:00 pm									
Was a Watercourse Reached? ☐ Yes X No							If YES, Volume Impacting the Watercourse.						
If a Watercou	rse was Im												
If a Watercourse was Impacted, Describe Fully.*													
N/A													
Describe Cause of Problem and Remedial Action Taken.* Look in flowling Contained within lined horm. Pingling will be repaired & returned to contained.													
Leak in flowline. Contained within lined berm. Pipeline will be repaired & returned to service													
Describe Are	Describe Area Affected and Cleanup Action Taken.*												
				ed berm. A vacuu	m truck	was used to	collect the standing	ng water	. The impa	cted material	was r	emoved and	
hauled to disposal.													
	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state,	or local lav	ws and/or regi	ulations.				•	•		•			
							OIL CONSERVATION DIVISION						
Signature:	(Ih	1//											
Printed Name	: Johnny T	itsworth		I	Approved by Environmental Specialist:								
Title: HSE Coordinator						Approval Date: 2/1/17 Ex			Expiration	piration Date: N/A			
						Conditions of Approval: N/A				Associated C			
							FINAL				Attached		
Date: 1/26/17 Phone: (432) 425-2891 FINAL													

* Attach Additional Sheets If Necessary