

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1633737079

OPERATOR

Initial Report X Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	GR 30 STATE #001	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-28356

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	30	23S	30E	330'	North	1980'	West	Eddy

Latitude 32.2822456 Longitude 103.9231949

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	90bbbs	Volume Recovered:	89bbbs
Source of Release:	Produced Water Tank	Date and Hour of Occurrence:	11/29/2016 10:43 pm	Date and Hour of Discovery:	11/29/2016 10:43 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Bratcher - NMOCD / Ms. Groves - SLO		
By Whom?		Date and Hour:	Wed 11/30/2016 9:04 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a hole in the produced water tank. The tank will be repaired.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho has had the free fluids and any impacted material inside the lined facility removed. The liner has been cleaned and the facility back in operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist:	
Title:	Senior HSE Coordinator	Approval Date:	2/22/17 Expiration Date: N/A
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:	Containment cleaned Liner inspected Attached <input type="checkbox"/>
Date:	January 19, 2017	Phone:	432-683-7443

* Attach Additional Sheets If Necessary

2RP-4023